



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS3/SMO22002696/Uvy3e2-1 Date: 10/05/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMZ 7811P	Veh. Inspected	SJB 278L
Policy No.	D21MTPV01007808	Coverage (\$)	0.00
Claim No.	CMTD2200976/LOR	Excess (\$)	0.00
Assign From	LORRIANCE WONG	Assign Date	25/04/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA5 SP (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JM6CR10F170106333	Colour	WHITE
Odometer	278247 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	TRIANGLE	6 mm
L/H Front Tyre	205/55 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/03/2022	Inspection Date	23/03/2022
Survey held at	Blk 13 Defu Lane 10 #01-432 Singapore 539194		
Repairer	KNW CAR SPRAY		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	