



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/SMO22002696/Uvy3-1

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: ~~CS3/SMO22002696/Uvy3~~
Date: ~~23/03/2022~~ 25/04/2022
Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMZ 7811P	Veh. Inspected	SJB 278L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2200976/LOR	Excess (\$)	0.00
Assign From	GRACE TEO LORRIANCE WONG	Assign Date	23/03/2022 25/04/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/03/2022	Inspection Date	23/03/2022
Survey held at	Blk 13 Defu Lane 10 #01-432 Singapore 539194		
Repairer	KNW CAR SPRAY		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.