

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22003839/APA3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000127
Claimant Vehicle No :	SMF7703Z	Insured Vehicle No :	SND5791E
Date of Loss:	24/04/2022	Nature of Claim:	TP
		Claim No:	2469510972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF7703Z		
Make & Model:	AUDI Q7, 3.0 TFSI QU (333 BHP) (A)	Engine No:	CRE050645
Reg. Date:	16/10/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ4M5GD011381
Colour:	Black	Odometer:	75137 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/45 R20	Rear Tyre Size:	285/45 R20
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,773.24	7,200.56	20,572.68	74.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,292.00	3,352.00	16,940.00	83.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	48,065.24	10,552.56	37,512.68	78.05
+ GST 7.00/7.00% (S\$)	3,364.57	738.68	2,625.89	78.05
Nett Amount (S\$)	51,429.81	11,291.24	40,138.57	78.05
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,898.69		

INSPECTION

Date of Assignment:	29/04/2022		
Date Inspected:	29/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,652.00 FS	*2,921.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	217.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	1,407.00 FS	*1,125.60 FS
4	1		*REAR BUMPER SPOILER -LOWER	Deformed	119.00 FS	*94.80 FS
5	1		*BOOT LID CONTROL UNIT	Not Necessary	429.00 FS	*- FS
6	1		*TAILGATE SENSOR LINE	Not Necessary	228.00 FS	*- FS
7	1		*REAR BUMPER REINFORCEMENT	Dented	1,506.00 FS	*1,204.80 FS
8	2		*REAR BUMPER SEAL -LH/RH	Not Necessary	32.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	206.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION -CENTER	Damaged	159.00 FS	*126.80 FS
11	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	142.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR -INNER /OUTER		390.24 FS	*390.24 FS
13	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
14	1		*REAR PARKING AID SENSOR -SIDE (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*SET REAR BUMPER WIRING	Not Necessary	715.00 FS	*- FS
16	1		*REAR BUMPER TAIL LIGHT -RH	Cut	402.00 FS	*321.60 FS
17	1		*TAIL LIGHT -RH	Not Necessary	2,279.00 FS	*- FS
18	1		*REAR LID	Repair	6,480.00 FS	*- FS
19	1		*REAR LID ATTACHMENT PARTS	Not Necessary	359.00 FS	*- FS
20	1		*REAR LID LOCK FLAP COVER	Not Necessary	13.00 FS	*- FS
21	1		*REAR LID LOCK STRIKER	Not Necessary	102.00 FS	*- FS
22	1		*REAR LID FLAP GASKET	Not Necessary	325.00 FS	*- FS
23	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
24	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
25	1		*Q7 EMBLEM	Necessary	104.00 FS	*82.80 FS
26	1		*TFSI EMBLEM	Necessary	104.00 FS	*82.80 FS
27	1		*QUATTRO EMBLEM	Necessary	104.00 FS	*82.80 FS
28	1		*REAR WINDSCREEN	Not Necessary	1,307.00 FS	*- FS
29	1		*PRIMER	Not Necessary	22.00 FS	*- FS
30	2		*REAR WINDSCREEN SPOILER -LH/RH	Not Necessary	514.00 FS	*- FS
31	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	794.00 FS	*635.20 FS
32	1		*REAR END PANEL	Not Necessary	668.00 FS	*- FS
33	1		*REAR END PANEL REINFORCEMENT	Not Necessary	1,506.00 FS	*- FS
34	1		*REAR LID LOCK STRIKER	Not Necessary	96.00 FS	*- FS
35	1		*EXHAUST TAIL PIPE TRIM -RH	Not Necessary	345.00 FS	*- FS
36	1		*STATIC MIXER	Not Necessary	12.00 FS	*- FS
37	1		*2- PACK EPOXY ADHESIVE	Not Necessary	122.00 FS	*- FS
38	1		*ALUMINIUM POWDER	Not Necessary	637.00 FS	*- FS
39	1		*HARDENER	Not Necessary	232.00 FS	*- FS
40	1		*ALUMINIUM PRIMER	Not Necessary	233.00 FS	*- FS
41	1		*CLEANING BLOCK	Not Necessary	96.00 FS	*- FS
42	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	*- FS
43	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
44	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
45	1		*ALUMINIUM FILLER POWDER	Not Necessary	280.00 FS	*- FS
46	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
47	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
48	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **27,773.24** **7,200.56**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	0.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	0.00
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	0.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,800.00	0.00
7	TO REMOVE AND REINSTALL REAR SEAT BACK REST HAT TRAY ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	0.00
8	TO SETUP AND PLACE THE VEHICLE IN ALUMINIUM BAY	New	1,800.00	0.00
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID TO CUT OUT AND WELD REAR END PANELLING REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	5,400.00	600.00
10	TO RESPRAY REAR UPPER BUMPER ,REAR LOWER BUMPER ,REAR LID ,REAR END PANELLING ,SPARE WHEEL HOUSING AND BOTH REAR WHEEL ABCH TRIMS	New	6,000.00	2,200.00
11	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	900.00	0.00
12	TO RENEW RHS REAR EXHAUST SILENCER TO ALIGN TO POSITION	New	480.00	0.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			20,292.00	3,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >