

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/00340/2022/JT
DATE : 26-Apr-22
WIP : 21528

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/4/222

YOUR INSURED VEH NO : SND 5791 E

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NG CHIA LIANG, BENJAMIN
ADDRESS : 29 MARINE CRESCENT
#09-25
SINGAPORE 440029
TELEPHONE : HP +65 97894277
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SP200142001
VEHICLE NO : **SMF 7703 Z**
MODEL CODE : AUDI Q7 3.0 TFSI QU
MODEL YEAR : 16/10/2015
ENGINE NO : CRE050645
CHASSIS NO : WAUZZZ4M5GD011381
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Apr-22
PLACE OF ACCIDENT : CAR PARK AT MARINE CRESCENT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 7703 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER REAR LID 'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,800.00	
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,800.00	
SUB TOTAL LABOUR CHARGES		:	\$ 5,520.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 7703 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO SETUP AND PLACE THE VEHICLE IN ALUMINIUM BAY.	S/N \$ 1,800.00	
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,400.00	
10	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID, REAR END PANELLING, SPARE WHEEL HOUSING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 6,000.00	
11	TO CARRY OUT ALUMINIUM PRIMER WORKS.	S/N \$ 900.00	
12	TO RENEW RHS REAR EXHAUST SILENCER. TO ALIGN TO POSITION.	S/N \$ 480.00	
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 20,292.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 7703 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,652.00	
2	REAR BUMPER FIXING PARTS	1	\$ 217.00	
3	REAR BUMPER SPOILER	1	\$ 1,407.00	
4	REAR BUMPER SPOILER - LOWER	1	\$ 119.00	
5	BOOT LID CONTROL UNIT	1	\$ 429.00	
6	TAILGATE SENSOR LINE	1	\$ 228.00	
7	REAR BUMPER REINFORCEMENT	1	\$ 1,506.00	
8	REAR BUMPER SEAL - LH / RH	2	\$ 32.00	
9	REAR BUMPER HOLDING STRAP	1	\$ 206.00	
10	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 159.00	
11	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 142.00	
12	REAR PARKING AID SENSOR - INNER / OUTER	2	TBC	
13	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00	
14	REAR PARKING AID SENSOR - SIDE	1	TBC	
15	REAR BUMPER WIRING SET	1	\$ 715.00	
16	REAR BUMPER TAIL LIGHT - RH	1	\$ 402.00	
17	TAIL LIGHT - RH	1	\$ 2,279.00	
18	REAR LID	1	\$ 6,480.00	
19	REAR LID ATTACHMENT PARTS	1	\$ 359.00	
20	REAR LID LOCK FLAP COVER	1	\$ 13.00	
SUB TOTAL SPARE PARTS		:	\$ 18,355.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 7703 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK STRIKER	1	\$ 102.00	
22	REAR LID FLAP GASKET	1	\$ 325.00	
23	REAR PACKING ADHESIVE	1	\$ 21.00	
24	AUDI EMBLEM	1	\$ 144.00	
25	Q7 EMBLEM	1	\$ 104.00	
26	TFSI EMBLEM	1	\$ 104.00	
27	QUATTRO EMBLEM	1	\$ 104.00	
28	REAR WINDSCREEN	1	\$ 1,307.00	
29	PRIMER	1	\$ 22.00	
30	REAR SPOILER - LH / RH	2	\$ 514.00	
31	REAR WHEEL ARCH COVER - LH / RH	2	\$ 794.00	
32	REAR END PANEL	1	\$ 668.00	
33	REAR END PANEL REINFORCEMENT	1	\$ 1,506.00	
34	REAR LID LOCK STRIKER	1	\$ 96.00	
35	EXHAUST TAIL PIPE TRIM - RH	1	\$ 345.00	
36	STATIC MIXER	1	\$ 12.00	
37	2-PACK EPOXY ADHESIVE	1	\$ 122.00	
38	ALUMINIUM POWDER	1	\$ 637.00	
39	HARDENER	1	\$ 232.00	
40	ALUMINIUM PRIMER	1	\$ 233.00	
SUB TOTAL SPARE PARTS		:	\$ 7,392.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 7703 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	CLEANING BLOCK	1	\$ 96.00	
42	ARYLIC SEALANT	S/N	\$ 180.00	
43	CAVITY WAX	S/N	\$ 140.00	
44	STONE CHIP	S/N	\$ 180.00	
45	ALUMINIUM FILLER POWDER	S/N	\$ 280.00	
46	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
47	REAR NO PLATE	S/N	\$ 60.00	
48	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 27,383.00	
TOTAL LABOUR CHARGES		:	\$ 20,292.00	
GRAND TOTAL		:	\$ 47,675.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT