

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
 Defu Industrial Park C, Singapore 539186
 Tel : 6343-0934 Fax : 6343-0921
 Email : jmartauto@gmail.com
 Registration No: 201400246D
 GST Reg. No: 201400246D

25-Apr-22

Our ref : TP/5110/22

Chia Kay Wee

TP China

Xiao Tony

RE : estimate cost for vehicle no : SJB 2277B

1 pc	116i emblem	<i>new</i>	\$	78.00	+
1 pc	rear bumper	<i>Delhd</i>		1,760.00	- 1350
1 pc	rear bumper rh retainer	<i>cracked</i>		210.00	* 140.
2 pcs	rear bumper reverse sensor	<i>2nd</i>		470.00	-
1 pc	rear bumper rh reflector	<i>cracked</i>		78.00	✓
1 pc	rear bumper tow hook cover	<i>Delhd</i>	2243	35.00	✓
1 pc	rear bumper reinforcement	<i>new</i>		785.00	*
1 pc	rear bumper chrome	<i>new</i>	2018.70	170.00	-
1 pc	rh taillamp	<i>new</i>		480.00	*
				<hr/> 4,066.00	
			less 10%	406.60	
				<hr/> 3,659.40	
Panel beating.			530	800.00	250
Spray painting.				800.00	250
Wiring.				30.00	✓
				<hr/> 5,289.40	
			Plus 7% GST	370.26	
				<hr/> 5,659.66	

SD : Five thousand six hundred fifty-nine & cents sixty-six only.

Admin Ly

P/P 25/04/22

03 Pages

Total: 2548.70

(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: