

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003861/KQY3Q2**Date:** 15/08/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00012842200

**Claimant Vehicle
No :** SFL37K**Insured
Vehicle No :** GBK9380L

Date of Loss: 21/04/2022

Nature of Claim: TP

Claim
No: SNM22D202772/C03/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFL37K**

Make & Model: AUDI Q5, 2.0 TFSI Quattro (A)

Engine No: CDN171668

Reg. Date: 23/02/2011 (Man. Year: 2010)

Chassis No: WAUZZZ8RXBA064867

Colour: Metallic Dark Blue

Odometer: 96615 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55Z R19

Rear Tyre Size: 235/55Z R19

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,204.60	1,967.76	4,236.84	68.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,160.00	1,240.00	51.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,604.60	3,127.76	5,476.84	63.65
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	8,604.60	2,450.00	6,154.60	71.53
+ GST 7.00/7.00% (S\$)	602.32	171.50	430.82	71.53
Nett Amount (S\$)	9,206.92	2,621.50	6,585.42	71.53

INSPECTION

Date of Assignment: 26/04/2022

Date Inspected: 23/05/2022 Inspected At:

Tropical Success Auto Care (HQ)
BLK 5032 Ang Mo Kio Avenue 3, #01-303
Industrial Park 2
Singapore 569535

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2022)
Parts:	M1-SUV	AUDI Q5 2.0 TFSI Quattro (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFL37K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Repair	1,774.00 FL	*- FL
2	1		*REAR LH FENDER	Repair	2,462.00 FL	*- FL
3	1		*REAR LH TAIL LAMP	Cut	728.00 FL	*651.00 FL
4	1		*REAR LH TAIL LAMP GASKET	Necessary	52.00 FL	*52.00 FL
5	1		*REAR BUMPER	Mtg Cracked	1,878.00 FL	*1,483.40 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (S\$)					6,894.00	2,186.40
- List Item Discount on L Items 10.00/10.00% (S\$)					689.40	218.64
Total Parts (S\$)					6,204.60	1,967.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & TRANSFER REAR LH DOOR NECESSARY ATTACHMENT SPARE PART ITEM. }	New	1,200.00	500.00
2	REMOVE & REFIT REAR LH DOOR }	New	0.00	0.00
3	REMOVE & TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PARTS ITEM }	New	0.00	0.00
4	REMOVE & REFIT REAR LH TAIL LAMNP ,REAR LH TAIL LAMP GASKET ,REAR BUMPER }	New	0.00	0.00
5	HEAT/WELD/CUT /RENEW REAR LH FENDER }	New	0.00	0.00
6	UNDER COATING ON REAR DAMAGED PORTION	New	200.00	0.00
7	PUTTY & PRIMER APPLICATION ,SRPAY PAINTING REAR LH DOOR ,RESR LH FENDER ,REAR BUMPER	New	1,000.00	660.00
Gross Labour Cost (\$\$)			2,400.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >