



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|--|--|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY | | | Ref: CC4/ASM22003869/Ega3q2 Date: 09/06/2022 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLW 1585J | Veh. Inspected | SDX 8188R | |
| Policy No. | GA605595 | Coverage (\$) | 0.00 | |
| Claim No. | S2M03ZE5 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 26/04/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | NISSAN KICKS | c.c | 1198 | |
| Engine No. | HIDDEN | Year of Reg. | 2021 | |
| Chassis No. | MNTFEAP15Z0000404 | Colour | BLUE | |
| Odometer | 21132 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/55 R17 | YOKOHAMA | 5 mm | |
| L/H Front Tyre | 205/55 R17 | YOKOHAMA | 5 mm | |
| R/H Rear Tyre | 205/55 R17 | YOKOHAMA | 5 mm | |
| L/H Rear Tyre | 205/55 R17 | YOKOHAMA | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 25/04/2022 | Inspection Date | 26/04/2022 | |
| Survey held at | TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |