

# OPTIMA WERKZ

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201212455W  
www.ow.sg

SINGAPORE

f /OptimaWerkz

● /OptimaWerkz

Date: 22/04/2022

Vehicle No: SKS90J

Model: TOYOTA ESTIMA AERAS PREMIUM 2.4

Chassis: ACR500188453-2015

Reg.Year: 2015

Third Party Insurer: EQ INSURANCE

Third Party Veh No: GBG633M

Date of Accident: 22/04/2022

Estimator: TING AN

Surveyor:

*Not Authorized  
611 Ring @ 5400h  
Passing Aera Party  
8 days*

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>1380</i>	1	B <sub>1</sub>	\$1,700.00
2	REAR TAILGATE "ESTIMA" EMBLEM <i>48</i>	1	Re	\$88.00
3	REAR TAILGATE "AERAS" EMBLEM <i>56</i>	1	Re	\$88.00
4	REAR WINDSCREEN MOULDING	1	Re	\$100.00
5	REAR TAILGATE INNER TRIM BOARD	1	Mfg. Re	\$500.00
6	REAR TAILGATE INNER LOCK	1	Re	\$475.00
7	REAR TAILGATE WEATHERSTRIP <i>311.70</i>	1	155-855W D/S/170	\$355.00
8	REAR TAILGATE LAMP LH	1	Re	\$488.00
9	REAR TAILGATE LAMP RH	1	Re	\$488.00
10	REAR TAILGATE CHROME MOULDING	1	Re	\$398.00
11	REAR BUMPER	1	B <sub>2</sub>	\$585.00
12	REAR BUMPER SIDE BRACKET LH	1	CM	\$90.00
13	REAR BUMPER SIDE BRACKET RH	1	CM	\$90.00
14	REAR BUMPER INNER BRACKET LH	1	CM	\$77.00
15	REAR BUMPER INNER BRACKET RH	1	CM	\$77.00
16	REAR END PANEL	1	B <sub>2</sub>	\$660.00
17	REAR END PANEL UPPER COVER	1	Re	\$275.00
18	REAR FLOOR PANEL	1	B <sub>2</sub>	\$757.00
19	REAR FENDER INNER TRIM BOARD LH	1	Re	\$838.00
20	REAR FENDER INNER TRIM BOARD RH <i>627.80</i>	1	Re/Mfg. CM	\$838.00
21	REAR FENDER LH	1		REPAIR
22	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$8,967.00
LESS 25%				-\$2,241.75
PARTS TOTAL				\$6,725.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1	Re	\$80.00
2	REAR BUMPER CLIPS	1	Re	\$60.00
3	REAR BUMPER REVERSE SENSOR	1	Re	\$300.00
4	REAR END PANEL JOINT SEALANT	1	Re	\$80.00
5	REAR END PANEL UPPER COVER CLIPS	1	Re	\$50.00
6	REAR FENDER INNER TRIM BOARD CLIPS LH	1	Re	\$50.00
7	REAR FENDER INNER TRIM BOARD CLIPS RH	1	Re	\$50.00
8	REAR NUMBER PLATE & HOLDER	1	Re	\$50.00
S/N TOTAL				\$720.00

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



# OPTIMA WERKZ™

SINGAPORE

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201212455W  
www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 22/04/2022  
 Vehicle No: SKS90J  
 Model: TOYOTA ESTIMA AERAS PREMIUM 2.4  
 Chassis: ACR500188453-2015  
 Reg.Year: 2015

Third Party Insurer: EQ INSURANCE  
 Third Party Veh No: GBG633M  
 Date of Accident: 22/04/2022  
 Estimator: TING AN  
 Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,500.00	900
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL, REAR FENDER LH, REAR FENDER RH & ETC.	\$1,500.00	800
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	90
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$120.00	20
<b>LABOUR TOTAL</b>	<b>\$3,640.00</b>	

TING AN **TOTAL** **\$11,085.25**

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

