

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EMPEROR LEASING PTE LTD
1 KUNG CHONG ROAD
SINGAPORE 159139

Contact : 65436968 88779765, 94528996

TP AXA.
Cecilia.

TAX INVOICE

Repair Code : CLM17164

Date in : 26/04/2022

Vehicle Num. : SLN7089H

Model : TOYOTA C-HR HYBRID 1.8S CVT

Chassis/Eng# : ZYX102014538/2ZR8039887

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER (LOWER) <i>del</i>	1	397.60	✓ 397.60
REAR BUMPER (TOP) <i>dist. del.</i>	1	690.00	✓ 690.00
REAR BUMPER END SEAL COVER RH <i>del</i>	1	82.25	✓ 82.25
REAR BUMPER RH LOWER COVER <i>del</i>	1	122.90	✓ 122.90
REAR BUMPER RH REFLECTOR <i>del</i>	1	89.00	✓ 89.00
REAR BUMPER RH REFLECTOR GARNISH <i>del</i>	1	187.00	✓ 187.00
REAR BUMPER SIDE RETAINER L/R <i>del</i>	2	112.20	112.20 224.40
REAR BUMPER TOW HOOK COVER <i>del</i>	1	27.70	✓ 27.70
REAR RH FENDER <i>del</i>	1	943.60	✓ 943.60
REAR RH FENDER AIR VENT <i>del</i>	1	73.60	✓ 73.60
REAR RH FENDER ARCH GARNISH <i>del</i>	1	175.15	✓ 175.15
REAR RH KNUCKLE ARM <i>del</i>	1	906.90	+ 906.90
REAR RH KNUCKLE ARM BEARING <i>del</i>	1	848.90	398 848.90
REAR RH LOWER ARM <i>del</i>	1	497.50	+ 497.50
REAR RH SHOCK ABSORBER <i>del</i>	1	134.70	+ 134.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EMPEROR LEASING PTE LTD
1 KUNG CHONG ROAD
SINGAPORE 159139

Contact : 65436968 88779765, 94528996

TAX INVOICE

Repair Code : CLM17164

Date in : 26/04/2022

Vehicle Num. : SLN7089H

Model : TOYOTA C-HR HYBRID 1.8S CVT

Chassis/Eng# : ZYX102014538/2ZR8039887

		Subtotal before discount	3298.40	5,401.20
	Percentage discount 25%		2473.80	1,350.30
		Sub-total 1		4,050.90
REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR BUMPER REFLECTOR GARNISH CHROME - SET	1	300.00	100	300.00
REAR BUMPER REVERSE SENSOR	1	280.00	200	280.00
REAR RH FENDER ARCH GARNISH CLIPS - SET	1	40.00	20	40.00
REAR TAILGATE AUTO OPENER SWITCH	1	280.00	+	280.00
		Subtotal before discount		950.00
	Percentage discount 0%			0.00
		Sub-total 2		950.00
		Parts-total		5,000.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,420.00

Parts & Labour Total

7,420.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item (s) is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Total: 4403.80

C/S: 3.5K

Adrian Lj
2/s 27/04/22

OS Rep