



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

GREAT AMERICAN INSURANCE COMPANY

Ref: CS3/GAI22003878/Bvy3e2

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date: 12/05/2022

Code: GAI

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

|                     |                  |                       |            |
|---------------------|------------------|-----------------------|------------|
| <b>Insured Veh.</b> | SLL 146H         | <b>Veh. Inspected</b> | SLC 9229R  |
| <b>Policy No.</b>   |                  | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | CLMOMVP000001202 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | SHERY WONG       | <b>Assign Date</b>    | 26/04/2022 |

### 2. Vehicle Particulars & Condition


|                         |                   |                     |            |
|-------------------------|-------------------|---------------------|------------|
| <b>Make &amp; Model</b> | KIA FORTE K3      | <b>c.c</b>          | 1591       |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2016       |
| <b>Chassis No.</b>      | KNAFX411MG5596214 | <b>Colour</b>       | RED        |
| <b>Odometer</b>         | 79707 KM          | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | FAIR              |                     |            |

### 3. Conditions of Tyres

|                       | Size       | Make     | Balance |
|-----------------------|------------|----------|---------|
| <b>R/H Front Tyre</b> | 205/55 R16 | TOURADOR | 6 mm    |
| <b>L/H Front Tyre</b> | 205/55 R16 | TOURADOR | 6 mm    |
| <b>R/H Rear Tyre</b>  | 205/55 R16 | TOURADOR | 6 mm    |
| <b>L/H Rear Tyre</b>  | 205/55 R16 | TOURADOR | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



### 5. General Information

|                       |   |                            |                         |
|-----------------------|---|----------------------------|-------------------------|
| <b>Accident Date</b>  | 24/04/2022  | <b>Inspect Date / Time</b> | 27/04/2022 ( 01:15 PM ) |
| <b>Survey held at</b> | FUNMASTERS PROMOTION<br>BLK 176, SIN MING DRIVE #03-21 SIN MING AUTOCARE SINGAPORE 575721 |                            |                         |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.  
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

### 5b. Estimate Days of Repair

|  |                       |
|--|-----------------------|
| <b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b> | <b>5 Working Days</b> |
|--|-----------------------|

Report Ref No. CS3/GAI22003878/Bvy3e2

#### Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.