

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

JBR LEASING PTE LTD
60 JALAN LAM HUAT #05-12 CARROS
CENTRE
SINGAPORE 737869

Contact : 85255530, 87575085

TP China

VERON

TAX INVOICE

Repair Code : CLM15512

Date in : 23/04/2022

Vehicle Num. : SLQ5781P

Model : HONDA VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31224799/LEB5924812

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
CENTER FLOOR PANEL UNDER COVER <i>lt</i>	1	350.30	✓ 350.30
FRONT BUMPER <i>Rgr</i>	1	801.70	✗ 801.70
FRONT BUMPER FOGLAMP GARNISH L/R <i>RH Del'd</i>	2	38.30	<i>38.30</i> 76.60
FRONT BUMPER LOWER LID <i>lt</i>	1	381.00	✓ 381.00
FRONT BUMPER LOWER SPOILER <i>new</i>	1	113.40	✗ 113.40
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	20.60	✗ 41.20
FRONT ENGINE CROSS MEMBER <i>Best</i>	1	804.50	✓ 804.50
FRONT ENGINE UNDER COVER <i>for</i>	1	120.60	✓ 120.60
FRONT FENDER INNER SHIELD L/R <i>new</i>	2	107.60	✗ 215.20
FRONT KNUCKLE ARM BEARING L/R <i>Dem'd</i>	2	201.70	✓ 403.40
FRONT KNUCKLE ARM L/R <i>new</i>	2	289.60	✗ 579.20
FRONT LOWER ARM L/R <i>Best</i>	2	350.70	✓ 701.40
FRONT SHOCK ABSORBER L/R <i>new</i>	2	277.60	✗ 555.20
FRONT WHEEL CAP L/R <i>LH wt</i>	2	165.30	<i>165.30</i> 330.60
FRONT WHEEL RIM L/R <i>LH Best</i>	2	405.40	<i>200/50</i> 810.80
REAR AXLE <i>Best</i>	1	1654.10	✓ 1,654.10
REAR BUMPER RH SIDE COVER <i>new</i>	1	195.00	✗ 195.00
REAR BUMPER RH SIDE RETAINER <i>Dem'd</i>	1	15.90	✓ 15.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JBR LEASING PTE LTD
 60 JALAN LAM HUAT #05-12 CARROS
 CENTRE
 SINGAPORE 737869

Contact : 85255530, 87575085

TAX INVOICE

Repair Code : CLM15512

Date in : 23/04/2022

Vehicle Num. : SLQ5781P

Model : HONDA VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31224799/LEB5924812

REAR FLOOR PANEL UNDER COVER	lit	1	250.00	✓	250.00
REAR RH DOOR	Dented	1	849.40	✓	849.40
REAR RH DOOR INNER TRIM BOARD	None	1	320.40	✓	320.40
REAR RH DOOR MECHANISM LOCK	Dented	1	289.40	✓	289.40
REAR RH DOOR WEATHER STRIP	None	1	111.70	+	111.70
REAR RH FENDER	Dented	1	851.70	✓	851.70
REAR RH FENDER ARCH GARNISH	lit	1	195.00	✓	195.00
REAR RH FENDER INNER SHIELD	torn	1	101.60	✓	101.60
REAR SHOCK ABSORBER L/R	None	2	201.40	+	402.80
REAR WHEEL BEARING L/R	RH - Dented	2	264.30	264.30	528.60
REAR WHEEL CAP L/R	lit	2	165.30	✓	330.60
REAR WHEEL RIM L/R	RH Bent	2	405.40	202.70	810.80
ROCKER GARNISH L/R	torn	2	377.50	✓	755.00
Subtotal before discount					13,947.10
Percentage discount 20%					2,789.42
Sub-total 1					11,157.68
FRONT 215/60R16 TYRE L/R	None	2	400.00	+	800.00
FRONT BUMPER CLIPS - SET	None	1	80.00	30	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n5l.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

JBR LEASING PTE LTD
60 JALAN LAM HUAT #05-12 CARROS
CENTRE
SINGAPORE 737869

Contact : 85255530, 87575085

TAX INVOICE

Repair Code : CLM15512

Date in : 23/04/2022

Vehicle Num. : SLQ5781P

Model : HONDA VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31224799/LEB5924812

FRONT FENDER INNER SHIELD CLIPS L/R - SET	2	50.00	+	100.00
REAR 215/60R16 TYRE L/R	2	400.00	+	800.00
REAR BUMPER CLIPS - SET	1	50.00	+	50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	+	50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET	1	40.00	20	40.00
REAR RH FENDER INNER SHIELD CLIPS L/R - SET	2	50.00	30	100.00
Subtotal before discount				2,020.00
Percentage discount 0%				0.00
Sub-total 2				2,020.00
Parts-total				13,177.68

LABOUR

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

Labour Total

4,450.00

Parts & Labour Total

17,627.68

total: 9697.44
L/S: 7-711 ✓

Adnan L
N/S 27/04/22

08 Days