

ASS. REC BY:

REF:

AIG / 220038821ke

Heath

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

CO / TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no/s: Optima

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNO 87822 Yr Regn: 01, 22

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda ^{AI} Verel c.c. 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 6983 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RV3 1002425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 22/4/22 D.O.I. 26/4/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>28/7</u>	<u>4636.94, Cash 15/8/22</u> <u>4636.94</u>

Date/Time, File Pass to? : Prel. Report : Final Report

1) Date/Time, File Return to? : Prel. Report : Final Report

2) Report Format : Lump Sum / I.B.I: (\$

Days Of Repair: _____ Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$: Interview (\$: Tech Invs (\$: Weekend (\$

Survey Fee	
Transportation	
S - RS - SI	
Fees	
Others	
TOTAL	

Date: 25/04/2022

Vehicle No: SND8782L

Model: HONDA VEZEL 1.5G CVT

Chassis: RV31002425-2021

Reg.Year: 2022

Not wither
Person B & pain

Third Party Insurer: AIG

Third Party Veh No: SDA8131A

Date of Accident: 22/04/2022

Estimator: TING AN

Surveyor:

84636.94

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE → <i>1203-50</i>	1		<i>By</i> \$1,440.00 ✓
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>na</i> \$60.00 ✓
3	REAR TAILGATE INNER LOCK	1		<i>R</i> \$352.00 X
4	REAR TAILGATE INNER TRIM BOARD	1		<i>in</i> \$226.00 X
5	REAR TAILGATE WEATHERSTRIP	1		<i>in</i> \$162.00 X
6	REAR WINDSCREEN MOULDING	1		<i>na</i> \$150.00 ✓
7	REAR BUMPER → <i>1150 SN 1657</i>	1	<i>1230-51W</i>	<i>By</i> \$1,850.00 ✓
8	REAR BUMPER SIDE BRACKET LH	1		<i>in</i> \$39.00 X
9	REAR BUMPER SIDE BRACKET RH	1		<i>in</i> \$39.00 X
10	REAR BUMPER REFLECTOR LH	1		<i>CM</i> \$54.00 ✓
11	REAR BUMPER LOWER DIFFUSER WITH GARNISH COVER	1	<i>825.30</i>	<i>na/di</i> \$1,053.00 ✓
12	REAR BUMPER REVERSE SENSOR → <i>0331-00</i>	<i>2</i>	\$540.00	\$1,080.00 ✓
13	REAR END PANEL UPPER COVER	1		<i>in</i> \$117.00 X
14	REAR END PANEL	1		<i>R</i> \$685.00 X
SUB TOTAL				\$7,307.00
LESS 20%				-\$1,461.40
PARTS TOTAL				\$5,845.60

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$80.00 ✓
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>na</i> \$40.00 X
3	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
4	REAR END PANEL SEALANT	1		<i>na</i> \$80.00 X
5	REAR END PANEL UPPER COVER CLIPS	1		<i>na</i> \$40.00 X
6	REAR NUMBER PLATE & HOLDER	1		<i>CM</i> \$50.00 ✓
S/N TOTAL				\$340.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date:	25/04/2022	Third Party Insurer:	AIG
Vehicle No:	SND8782L	Third Party Veh No:	SDA8131A
Model:	HONDA VEZEL 1.5G CVT	Date of Accident:	22/04/2022
Chassis:	RV31002425-2021	Estimator:	TING AN
Reg.Year:	2022	Surveyor:	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.	\$700.00	<i>400</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.	\$700.00	<i>400</i>
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING. TO EFFECT REPLACE OF REAR TAILGATE.	\$150.00	<i>120</i>
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS .	\$120.00	<i>60</i>
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	<i>60</i>
TO TUFF KOTE & UNDERSEAL MATERIALS .	\$120.00	<i>30</i>
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	<i>nn</i> X
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$80.00	<i>20</i>
LABOUR TOTAL	\$2,120.00	

TING AN	TOTAL	\$8,305.60
---------	--------------	-------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date: 14/05/2022
Vehicle No: SND8782L
Model: HONDA VEZEL 1.5G CVT
Chassis: RV31002425-2021
Reg.Year: 2022

Third Party Insurer: AIG
Third Party Veh No: SDA8131A
Date of Accident: 22/04/2022

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR KEY ANTENNA SENSOR	1		<i>CM</i> \$103.00
SUB TOTAL				\$103.00
LESS 20%				-\$20.60
PARTS TOTAL				\$82.40

TING AN	TOTAL	\$82.40
---------	-------	---------

Finalize:

Parts: \$417.60

Supp: \$82.40

Nett: \$135

labour: \$1180

P/P: \$5515

Head office

8 Kung Chong Road Singapore 160142
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6464 9919 | Fax: (+65) 6481 1593

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

