

Date: 25/04/2022

Vehicle No: SND8782L

Model: HONDA VEZEL 1.5G CVT

Chassis: RV31002425-2021

Reg.Year: 2022

Third Party Insurer: AIG

Third Party Veh No: SDA8131A

Date of Accident: 22/04/2022

Estimator: TING AN

Surveyor:

Not Notified
Primary B & pain
4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$1,440.00 ✓
2	REAR TAILGATE "VEZEL " EMBLEM	1		<i>By</i> \$60.00 ✓
3	REAR TAILGATE INNER LOCK	1		<i>By</i> \$352.00 X
4	REAR TAILGATE INNER TRIM BOARD	1		<i>By</i> \$226.00 X
5	REAR TAILGATE WEATHERSTRIP	1		<i>By</i> \$162.00 X
6	REAR WINDSCREEN MOULDING	1		<i>By</i> \$150.00 ✓
7	REAR BUMPER	1		<i>By</i> \$1,850.00 ✓
8	REAR BUMPER SIDE BRACKET LH	1		<i>By</i> \$39.00 X
9	REAR BUMPER SIDE BRACKET RH	1		<i>By</i> \$39.00 X
10	REAR BUMPER REFLECTOR LH	1		<i>CM</i> \$54.00 ✓
11	REAR BUMPER LOWER DIFFUSER WITH GARNISH COVER	1		<i>Ref/Dir</i> \$1,053.00 ✓
12	REAR BUMPER REVERSE SENSOR	2	\$540.00	\$1,080.00 7
13	REAR END PANEL UPPER COVER	1		<i>By</i> \$117.00 X
14	REAR END PANEL	1		<i>By</i> \$685.00 X
SUB TOTAL				\$7,307.00
LESS 20%				-\$1,461.40
PARTS TOTAL				\$5,845.60

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>By</i> \$80.00 <i>4500</i>
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>By</i> \$40.00 X
3	REAR BUMPER CLIPS	1		<i>By</i> \$50.00 ✓
4	REAR END PANEL SEALANT	1		<i>By</i> \$80.00 X
5	REAR END PANEL UPPER COVER CLIPS	1		<i>By</i> \$40.00 X
6	REAR NUMBER PLATE & HOLDER	1		<i>CM</i> \$50.00 <i>4500</i>
S/N TOTAL				\$340.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 25/04/2022
Vehicle No: SND8782L
Model: HONDA VEZEL 1.5G CVT
Chassis: RV31002425-2021
Reg.Year: 2022

Third Party Insurer: AIG
Third Party Veh No: SDA8131A
Date of Accident: 22/04/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC. 400/ \$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC. 400/ \$700.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING. TO EFFECT REPLACE OF REAR TAILGATE. 120/ \$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. 60/ \$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. 60/ \$100.00

TO TUFF KOTE & UNDERSEAL MATERIALS. 30/ \$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY. 7/ \$150.00

TO CHECK WIRING & CENTRAL LOCKING SYSTEM. 20/ \$80.00

LABOUR TOTAL **\$2,120.00**

TING AN **TOTAL** **\$8,305.60**

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 668047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

