

Date : 26/04/2022

TO: India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Our Customer : Poh Liong Yan
Vehicle No : SLV9447C
Model : Honda Vezel 1.5X CVT
Manufacture Year : 2018
Date of Accident : 25/04/2022
Total Estimate Repair Days : 7
Total Pages : 2

Attn : Motor Claims Department
Fax : 6224 4174

Re: Repair Estimate For Third Party Claim against GBB6803B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Tail gate <i>Distorted</i>	1	\$1,300.90	\$1,300.90	<i>1100</i>
2	Tail gate absorbers <i>new</i>	2	\$235.20	\$470.40	<i>+</i>
3	Tail gate hinges <i>new</i>	2	\$68.00	\$136.00	<i>+</i>
4	Tail gate weatherstrip <i>new</i>	1	\$185.20	\$185.20	<i>+</i>
5	Tail gate "Honda" logo <i>new</i>	1	\$55.60	\$55.60	<i>✓</i>
6	Tail gate "Vezel" emblem <i>new</i>	1	\$57.60	\$57.60	<i>✓</i>
7	Tail gate reflector RH <i>new</i>	1	\$290.70	\$290.70	<i>✓</i>
8	Tail gate reflector LH <i>new</i>	1	\$290.70	\$290.70	<i>✓</i>
9	Tail gate lock <i>new</i>	1	\$180.40	\$180.40	<i>✓</i>
10	Tail gate lower catch <i>new</i>	1	\$42.00	\$42.00	<i>+</i>
11	Tail gate trimboard <i>new</i>	1	\$246.00	\$246.00	<i>✓</i>
12	Rear windscreen glass moulding <i>new</i>	4	\$75.40	\$301.60	<i>✓</i>
13	Rear windscreen <i>Shattered</i>	1		\$0.00	<i>1080</i>
14	Rear bumper <i>Deland</i>	1	\$963.20	\$963.20	<i>745</i>
15	Rear bumper side retainer RH <i>new</i>	1	\$33.60	\$33.60	<i>✓</i>
16	Rear bumper side retainer LH <i>new</i>	1	\$33.60	\$33.60	<i>✓</i>
17	Rear bumper reflector LH <i>new</i>	1	\$151.20	\$151.20	<i>+</i>
18	Rear bumper centre guard chrome <i>Best</i>	1		\$0.00	<i>250</i>
19	Rear bumper pad <i>new</i>	1		\$0.00	<i>+</i>
20	Rear bumper pad centre chrome <i>new</i>	1		\$0.00	<i>280</i>
21	Rear end panel <i>new</i>	1	\$530.80	\$530.80	<i>+</i>
22	Rear end panel garnish <i>new</i>	1	\$114.00	\$114.00	<i>✓</i>
23	Spare tyre panel <i>new</i>	1	repair	repair	<i>+</i>
24	Spare tyre board <i>new</i>	1	\$450.20	\$450.20	<i>+</i>
25	Tools foam <i>new</i>	1		\$0.00	<i>+</i>
			Total	\$5,833.70	
			Less 20%	\$1,166.74	
			Sub Total 1	\$4,666.96	
A.	Spare Parts (S/Nett)				
1	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	<i>30</i>
2	Reverse sensor (set) <i>new</i>	1	\$250.00	\$250.00	<i>200</i>
3	Sealant <i>new</i>	1	\$60.00	\$60.00	<i>+</i>
4	Rear end panel garnish clip <i>new</i>	7	\$5.00	\$35.00	<i>10</i>
5	Rear number plate w/casing <i>new</i>	1	\$70.00	\$70.00	<i>+</i>
	<i>Rear camera</i>				
	<i>Deland</i>				
			Sub-Total 2	\$465.00	

620

Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
Total for Parts				\$5,131.96	
B.	Labour				
1	To check wiring.			\$60.00 30	
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00 600	
3	Spray painting all affected parts & areas.			\$800.00 600	
4	To spray anti-rust undercoat.			\$60.00 40	
5	To remove and replace rear windscreen glass			\$150.00 120	
	To clean shattered glass.			\$100.00 60	
6	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00 60	
Total Labour				\$2,220.00	
Total Repair Cost				\$7,351.96	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Admin

2/5 26/04/22

04 Days

total 6177.04

2/5: 4.9k

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No