

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22003886/GNY3Q2**Date:** 27/12/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP315686
Claimant Vehicle No :	SNA2411M	Insured Vehicle No :	SKX7398A
Date of Loss:	22/04/2022	Nature of Claim:	TP
		Claim No:	MPC03359/JW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA2411M	Engine No:	2ZR2H37264
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU203093200
Reg. Date:	14/06/2021 (Man. Year: 2020)	Odometer:	75910 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,109.25	2,775.00	3,334.25	54.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,740.00	1,630.00	48.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,479.25	4,515.00	4,964.25	52.37
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	9,479.25	3,600.00	5,879.25	62.02
+ GST 7.00/7.00% (S\$)	663.55	252.00	411.55	62.02
Nett Amount (S\$)	10,142.80	3,852.00	6,290.80	62.02

INSPECTION

Date of Assignment:	26/04/2022	
Date Inspected:	27/04/2022	Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA2411M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Buckled	1,359.00 FL	*1,264.00 FL
2	1		*FRONT DOOR INNER LOCK RH	Not Necessary	312.00 FL	*- FL
3	1		*FRONT DOOR REGULATOR RH	Not Necessary	587.00 FL	*- FL
4	1		*FRONT DOOR FRAME BLACK STICKER SET RH	Necessary	212.00 FL	*212.00 FL
5	1		*REAR DOOR RH	Buckled	1,359.00 FL	*1,294.00 FL
6	1		*REAR DOOR INNER LOCK RH	Not Necessary	312.00 FL	*- FL
7	1		*REAR DOOR REGULATOR RH	Not Necessary	587.00 FL	*- FL
8	1		*REAR DOOR FRAME GARNISH RH	Not Necessary	159.00 FL	*- FL
9	1		*REAR DOOR FRAME BLACK STICKER RH	Necessary	89.00 FL	*89.00 FL
10	1		*SIDE SKIRTING RH	Deformed	898.00 FL	*721.00 FL
11	1		*REAR FENDER RH	Repair	798.00 FL	*- FL
12	1		*REAR FENDER COWLING RH	Not Necessary	198.00 FL	*- FL
13	1		*REAR WHEEL BEARING RH	Not Necessary	211.00 FL	*- FL
14	1		*REAR BUMPER	Repair	798.00 FL	*- FL
15	1		*FRONT DOOR INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
16	1		*REAR DOOR INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
17	1		*REAR HUB CAP RH	Cut	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,079.00	3,670.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,969.75	895.00
Total Parts (S\$)	6,109.25	2,775.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIR REAR DOOR MECHANISM	New	150.00	60.00
2	CHECK WIRING	New	100.00	20.00
3	REMOVE AND REFIT REAR UPHOLSTERY AND SEAT	New	300.00	0.00
4	REMOVE AND REFIR REAR QUARTER GLASS RH	New	100.00	0.00
5	REMOVE AND REFIR REAR UNDERCARRIAGE	New	600.00	0.00
6	CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
7	PANEL BEAT EFFECTED AREAS	New	1,000.00	700.00
8	RESPRAY EFFECTED AREAS	New	1,000.00	900.00
Gross Labour Cost (S\$)			3,370.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >