



MY CAR CONSULTANT PT. LTD

Reg no.: 2016058782

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 5737896

HP: 98888885

Estimation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: 26/4/2022

Signature: SNA2411M

Vehicle: TOYOTA PRIUS

INS: NTUC

67 days. Gue Rina
4/5 82880282
After repair 27/4/22

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT DOOR RH / Bue	1	\$ 1,359.00	\$ 1,359.00
2	FRONT DOOR INNER LOCK RH X / Bue	1	\$ 312.00	\$ 312.00
3	FRONT DOOR REGULATOR RH X / Bue	1	\$ 587.00	\$ 587.00
4	FRONT DOOR FRAME BLACK STICKER SET RH / Bue	1	\$ 212.00	\$ 212.00
5	REAR DOOR RH / Bue	1	\$ 1,359.00	\$ 1,359.00
6	REAR DOOR INNER LOCK RH X / Bue	1	\$ 312.00	\$ 312.00
7	REAR DOOR REGULATOR RH X / Bue	1	\$ 587.00	\$ 587.00
8	REAR DOOR FRAME GARNISH RH X / Bue	1	\$ 159.00	\$ 159.00
9	REAR DOOR FRAME BLACK STICKER RH / Bue	1	\$ 89.00	\$ 89.00
10	SIDE SKIRTING RH / Bue	1	\$ 898.00	\$ 898.00
11	REAR FENDER RH X / Bue	1	\$ 798.00	\$ 798.00
12	REAR FENDER COWLING RH X / Bue	1	\$ 198.00	\$ 198.00
13	REAR WHEEL BEARING RH X / Bue	1	\$ 211.00	\$ 211.00
14	REAR BUMPER X / Bue	1	\$ 798.00	\$ 798.00
	TOTAL PART			\$ 7,879.00
	LIST DOWN	25%		\$ 1,969.75
	AFTER LIST DOWN			\$ 5,909.25
SPECIAL NETT				
1	FRONT DOOR INNER TRIM CLIPS / Bue	1	\$ 50.00	\$ 50.00
2	REAR DOOR INNER TRIM CLIPS / Bue	1	\$ 50.00	\$ 50.00
3	REAR HUB CAP RH / Bue	1	\$ 100.00	\$ 100.00
	TOTAL AMOUNT			\$ 200.00
LABOUR				
1	CHECK WIRING	1	\$ 100.00	\$ 100.00
2	REMOVE AND REPAIR REAR DOOR MECHANISM	1	\$ 150.00	\$ 150.00
3	REMOVE AND REPAIR REAR UPHOLSTERY AND SEAT	1	\$ 300.00	\$ 300.00
4	REMOVE AND REPAIR REAR QUARTER GLASS RH	1	\$ 100.00	\$ 100.00
5	REMOVE AND REPAIR REAR UNDERCARRIAGE	1	\$ 600.00	\$ 600.00
6	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
7	PANEL BEAT EFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
8	REPAIR EFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
	TOTAL AMOUNT			\$ 3,370.00
total - 4515			Parts Replacement Amount	\$ 6,109.25
L/S - 3612			Total Amount for Labour	\$ 3,370.00
= 3600			Total Amount	\$ 9,479.25

1264 ✓

X

X

✓

1294 ✓

X

X

X

✓

721 ✓

X

X

X

X

X

3580

-25%

2685

20

20

50

90

20

60

X

X

X

X

60

700

800

1740