

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

NEO SOON HUAT
 BLK 520C TAMPINES CENTRAL 8 #13-65
 SINGAPORE 523520

Contact : 93675418

TP Chim
 Xiao Chen

TAX INVOICE

Repair Code : CLM15515
 Date in : 25/04/2022
 Vehicle Num. : SMP6165E
 Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (AUTO)
 Chassis/Eng# : MR053REH604598611/1ZR0E02306

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
PETROL LID COVER RIVET <i>new</i>	2	3.80	+ 7.60
REAR BUMPER <i>torn</i>	1	556.40	✓ 556.40
REAR BUMPER LH END SEAL COVER <i>new</i>	1	55.10	+ 55.10
REAR BUMPER SIDE RETAINER L/R <i>RH could</i>	2	109.30	109.30 218.60
REAR LH BEARING HUB <i>Damaged</i>	1	960.50	762 960.50
REAR LH DOOR <i>Dented</i>	1	1248.50	✓ 1,248.50
REAR LH DOOR FRAME BLACK STICKER <i>new</i>	1	43.50	✓ 43.50
REAR LH DOOR INNER PLASTIC SEAL COVER	1	33.20	+ 33.20
REAR LH DOOR RUBBER GUIDE STOPPER	1	10.50	+ 10.50
REAR LH DOOR VERTICAL GARNISH <i>new</i>	1	93.00	+ 93.00
REAR LH DOOR WEATHER STRIP	1	155.00	+ 155.00
REAR LH FENDER <i>Repair</i>	1	1149.00	+ 1,149.00
REAR LH SPORT RIM <i>cut</i>	1	2190.40	1400 (SA) 2,190.40
REAR WINDSCREEN GLASS MOULDING <i>new</i>	1	41.10	+ 41.10
Subtotal before discount			6,762.40
Percentage discount 25%			1,690.60
Sub-total 1			5,071.80
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

NEO SOON HUAT
 BLK 520C TAMPINES CENTRAL 8 #13-65
 SINGAPORE 523520

Contact : 93675418

TAX INVOICE

Repair Code : CLM15515
 Date in : 25/04/2022
 Vehicle Num. : SMP6165E
 Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (AUTO)
 Chassis/Eng# : MR053REH604598611/1ZR0E02306

REAR BUMPER LH END SEAL COVER CLIPS - SET	<i>new</i>	1	30.00	30.00	*
REAR LH DOOR CHROME MOULDING - SET	<i>new</i>	1	80.00	80.00	*
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	50.00	*
REAR LH DOOR VISOR GARNISH - SET	<i>new</i>	1	250.00	250.00	<i>120</i>
REAR LH TYRE	<i>new</i>	1	450.00	450.00	*
REAR WINDSCREEN GLASS SEALANT	<i>new</i>	1	60.00	60.00	*
Subtotal before discount				970.00	
Percentage discount 0%				0.00	
Sub-total 2				970.00	
Parts-total				6,041.80	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓	60.00
To remove and refit rear windscreen(to FR)	*	150.00
To remove, reinstall rear suspension and undercarriage part. (to FR)	<i>80</i>	150.00
To road test driving, check and resetting wheel alignments system.	<i>80</i>	100.00
To remove, reinstall petrol tank. (to FR)	*	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>40</i>	100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	<i>80</i>	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>600</i>	850.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NEO SOON HUAT
BLK 520C TAMPINES CENTRAL 8 #13-65
SINGAPORE 523520

Contact : 93675418

TAX INVOICE

Repair Code : CLM15515

Date in : 25/04/2022

Vehicle Num. : SMP6165E

Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (AUTO)

Chassis/Eng# : MR053REH604598611/1ZR0E02306

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	1590	600 900.00
		50 80.00
Labour Total		2,570.00
Parts & Labour Total		8,611.80

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 04/05/22

05 Days.

total: 5025.77

L/S: AK

AK