

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2279P

17.04.2022

MAKE REG. 20.12.2017

MODEL I-40

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER TOP BRACKET LH/RH		\$22.40	\$44.80
1	FRONT BUMPER			\$1,052.20
1	FRONT BUMPER REINFORCEMENT			\$588.40
1	FRONT BUMPER GRILLE LH/RH		\$187.20	\$374.40
1	FRONT HEAD LAMP SUPPORT PANEL			\$907.00
1	FRONT RADIATOR GRILLE			\$1,480.00
10	BUMPER CLIPS		\$2.20	\$22.00
	SUB TOTAL			\$4,468.80
	LESS 20%			\$893.76
				\$3,575.04
1	FRONT NUMBER PLATE			\$50.00
				\$45.00
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$300.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,020.00
	ESTIMATE TOTAL			\$4,640.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2279P

17.04.2022

MAKE REG: 20.12.2017

MODEL HYU- I40

Type

CHIANG/ NTUC

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER		\$553.00
1	REAR BUMPER LOWER COVER		\$228.00
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	REAR BUMPER BRACKET RH		\$35.60
1	REAR BUMPER REINFORCEMENT		\$428.40
2	REAR BUMPER REFLECTOR LH/RH	\$32.00	\$64.00
	SUB TOTAL		\$1,331.00
	20.00%		\$266.20
	DISCOUNTED TOTAL		\$1,064.80
1	REAR BUMPER MAT		\$50.00
1	REAR REVERSE SENSOR		\$135.70
			\$172.13
	Labour Charge		
	Panel Beating		\$560.00
	Spray Painting Charge		\$300.00
	Remove/refix reverse sensor		\$60.00
	Check Lighting & Wiring		\$40.00
	TOTAL LABOUR		\$960.00
	ESTIMATE TOTAL		\$2,196.93
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thuan

82235469

14/4/22 17/5

L/S 3days up