

Our Job Ref No : 305512995  
Date : 28.04.2022

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

**FINALIZATION FORM**

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC2279P

17.04.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC SJQ8869A
2. The finalized amount shall be:
- (a) Spare Parts after List discount \_\_\_\_\_
- (b) Labour Charges \_\_\_\_\_
- Total for Part-By-Part Repair Cost** \_\_\_\_\_
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
Final Lumpsum Repair cost \$1,500.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : THEVAN

Date : 28/4/22

**For Official Use Only**

| Item   | Amount        | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|---------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |               | YES                         |                        |         |
| 2. Loss of Income Paid                               | -             | N                           |                        |         |
| 3. Survey Fees                                       | -             | -                           |                        |         |
| 4. LTA Search Fee                                    | \$7.49/\$2.00 | YES                         |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |               |                             |                        |         |
| 6. Overrun   |               |                             |                        |         |

Remarks:

\_\_\_\_\_

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC2279P

17.04.2022

MAKE REG. 20.12.2017

MODEL I-40

CHIANG/NTUC

| Qty | Parts Description/ Labour      | Type | Unit Price | Amount            |
|-----|--------------------------------|------|------------|-------------------|
| 1   | FRONT BUMPER TOP BRACKET LH/RH |      | \$22.40    | \$44.80           |
| 1   | FRONT BUMPER                   |      |            | \$1,052.20        |
| 1   | FRONT BUMPER REINFORCEMENT     |      |            | \$588.40          |
| 1   | FRONT BUMPER GRILLE LH/RH      |      | \$187.20   | \$374.40          |
| 1   | FRONT HEAD LAMP SUPPORT PANEL  |      |            | \$907.00          |
| 1   | FRONT RADIATOR GRILLE          |      |            | \$1,480.00        |
| 10  | BUMPER CLIPS                   |      | \$2.20     | \$22.00           |
|     | <b>SUB TOTAL</b>               |      |            | <b>\$4,468.80</b> |
|     | <b>LESS 20%</b>                |      |            | <b>\$893.76</b>   |
|     |                                |      |            | <b>\$3,575.04</b> |
|     |                                |      |            |                   |
|     |                                |      |            |                   |
| 1   | FRONT NUMBER PLATE             |      |            | \$50.00           |
|     |                                |      |            | <b>\$45.00</b>    |
|     | <b>Labour Charge</b>           |      |            |                   |
|     | Panel Beating                  |      |            | \$600.00          |
|     | Spray Painting Charge          |      |            | \$300.00          |
|     | Tuff Kote                      |      |            | \$60.00           |
|     | Check Lighting                 |      |            | \$60.00           |
|     | <b>TOTAL LABOUR</b>            |      |            | <b>\$1,020.00</b> |
|     | <b>ESTIMATE TOTAL</b>          |      |            | <b>\$4,640.04</b> |
|     |                                |      |            |                   |
|     |                                |      |            |                   |
|     |                                |      |            |                   |
|     |                                |      |            |                   |

KSR  
 KR  
 XSR  
 XSR  
 XSR  
 XSR  
 XSR  
 XSR  
 CR9  
 280  
 250  
 30  
 30

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC2279P

17.04.2022

MAKE REG: 20.12.2017

MODEL HYU- I40

Type

CHIANG/ NTUC

| Qty  | Parts Description/ Labour   | Unit Price | Amount            |
|--|-----------------------------|------------|-------------------|
| 1  | REAR BUMPER COVER           |            | \$553.00          |
| 1  | REAR BUMPER LOWER COVER     |            | \$228.00          |
| 10   | REAR BUMPER CLIPS           | \$2.20     | \$22.00           |
| 1  | REAR BUMPER BRACKET RH      |            | \$35.60           |
| 1  | REAR BUMPER REINFORCEMENT   |            | \$428.40          |
| 2  | REAR BUMPER REFLECTOR LH/RH | \$32.00    | \$64.00           |
|  | <b>SUB TOTAL</b>            |            | <b>\$1,331.00</b> |
|  | <b>20.00%</b>               |            | <b>\$266.20</b>   |
|  | <b>DISCOUNTED TOTAL</b>     |            | <b>\$1,064.80</b> |
| 1  | REAR BUMPER MAT             |            | \$50.00           |
| 1  | REAR REVERSE SENSOR         |            | \$135.70          |
|  |                             |            | <b>\$172.13</b>   |
|  | <b>Labour Charge</b>        |            |                   |
|  | Panel Beating               |            | \$560.00          |
|  | Spray Painting Charge       |            | \$300.00          |
|  | Remove/refix reverse sensor |            | \$60.00           |
|  | Check Lighting & Wiring     |            | \$40.00           |
|  | <b>TOTAL LABOUR</b>         |            | <b>\$960.00</b>   |
|  | <b>ESTIMATE TOTAL</b>       |            | <b>\$2,196.93</b> |
| This is an initial estimate based on a visual inspection of the <u>above vehicle</u> . The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                             |            |                   |

Thuan  
82235469  
19/4/22 1715  
L/S 3days up