

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BOON LIANG
83 YISHUN AVE 11 #09-28
SINGAPORE 768864

TAX INVOICE

Contact : 91062119

TP chimer
Denise
Repair Code : CLM15511
Date in : 23/04/2022
Vehicle Num. : SLP5632S
Model : SUBARU FORESTER 2.0XT CVT AWD SR
Chassis/Eng# : JF1SJGK85HG088926/FA20B989871

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delud</i>	1	640.30	✓ 640.30
REAR BUMPER REFLECTOR L/R <i>new</i>	2	52.80	+ 105.60
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	420.90	✓ 420.90
REAR BUMPER SIDE RETAINER L/R <i>Cracked</i>	2	16.30	✓ 32.60
REAR BUMPER TOP GARNISH <i>Delud</i>	1	330.20	✓ 330.20
REAR BUMPER TOW HOOK COVER <i>Delud</i>	1	24.30	✓ 24.30
REAR END PANEL <i>new</i>	1	320.40	+ 320.40
REAR END PANEL INNER TOP GARNISH <i>new</i>	1	60.90	+ 60.90
REAR TAILGATE <i>Dented</i>	1	1072.00	✓ 1,072.00
REAR TAILGATE 'AWD' EMBLEM	1	48.00	✓ 48.00
REAR TAILGATE 'FORESTER' EMBLEM	1	72.40	✓ 72.40
REAR TAILGATE 'LOGO' EMBLEM	1	88.40	✓ 88.40
REAR TAILGATE 'SUBARU' EMBLEM	1	72.40	✓ 72.40
REAR TAILGATE 'XT' EMBLEM	1	35.00	✓ 35.00
REAR TAILGATE HINGES L/R <i>new</i>	2	57.30	+ 114.60
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	9.80	+ 19.60
REAR TAILGATE INNER TRIM BOARD <i>Cracked</i>	1	180.40	✓ 180.40
REAR TAILGATE MECHANISM LOCK <i>Dented</i>	1	560.90	✓ 560.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN BOON LIANG
 83 YISHUN AVE 11 #09-28
 SINGAPORE 768864

Contact : 91062119

TAX INVOICE

Repair Code : CLM15511

Date in : 23/04/2022

Vehicle Num. : SLP5632S

Model : SUBARU FORESTER 2.0XT CVT AWD SR

Chassis/Eng# : JF1SJGK85HG088926/FA20B989871

REAR TAILGATE NUMBER PLATE LAMP L/R	<i>MEM</i>	2	34.30	<i>+</i>	68.60
REAR TAILGATE OUTER GARNISH	<i>cancel</i>	1	248.70	<i>✓</i>	248.70
REAR TAILGATE WEATHER STRIP	<i>NEW</i>	1	120.40	<i>+</i>	120.40
REAR TAILGATE WINDSCREEN MOULDING	<i>NEW</i>	1	149.80	<i>✓</i>	149.80
REAR TAILLAMP LOWER BRACKET L/R	<i>cancel</i>	2	24.30	<i>✓</i>	48.60
Subtotal before discount					4,835.00
Percentage discount 20%					967.00
Sub-total 1					3,868.00
REAR BUMPER CLIPS - SET	<i>NEW</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>	1	280.00	<i>20</i>	280.00
REAR TAILGATE CAMERA	<i>Damaged</i>	1	800.00	<i>380</i>	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>NEW</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE NUMBER PLATE	<i>3 NEW</i>	1	25.00	<i>+</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER		1	50.00	<i>+</i>	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>NEW</i>	1	50.00	<i>20</i>	50.00
REAR TAILGATE WINDSCREEN SEALANT	<i>NEW</i>	1	80.00	<i>60</i>	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN BOON LIANG
 83 YISHUN AVE 11 #09-28
 SINGAPORE 768864

Contact : 91062119

TAX INVOICE

Repair Code : CLM15511
 Date in : 23/04/2022
 Vehicle Num. : SLP5632S
 Model : SUBARU FORESTER 2.0XT CVT AWD SR
 Chassis/Eng# : JF1SJGK85HG088926/FA20B989871

Subtotal before discount	1,415.00
Percentage discount 0%	0.00
Sub-total 2	1,415.00
Parts-total	5,283.00

710

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	x. 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1230 500 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	500 1,000.00
To apply anti-rust chemical on repaired and replaced panel.	30 100.00
To remove, reinstall tailgate mechanism and check for function	80.00
Labour Total	2,510.00
Parts & Labour Total	7,793.00

Adrian Lim
 W/S 26/04/22

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

04 days
 total: 5027.20
 W/S: AK. ✓