



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                       |  |  |                            |            |
|---|--|--|----------------------------|------------|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877 |  |  | Ref: CS/FCI22003890/Evy3s2 |            |
|   |  |  | Date: 26/05/2022           |            |
|   |  |  | Code: FCI2                 |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                       |  |  |                            |            |
|   | Insured Veh.   | XD 4120E   | Veh. Inspected             | SKJ 1368A  |
|   | Policy No.   |  | Coverage (\$)              | 0.00       |
|   | Claim No.  | D22001204MFCV  | Excess (\$)                | 0.00       |
|   | Assign From  | VICALPEH   | Assign Date                | 26/04/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |  |                            |            |
|   | Make & Model   | MERCEDES BENZ E200   | c.c                        | 1991       |
|   | Engine No.   | HIDDEN   | Year of Reg.               | 2018       |
|   | Chassis No.  | WDD2130422A546316  | Colour                     | BLACK      |
|   | Odometer   | 70621 KM   | Steering                   | IN ORDER   |
|   | Brakes   | IN ORDER   | Modification               | SPORTS RIM |
|   | General  | GOOD   |                            |            |
| <b>3. Conditions of Tyres</b>   |  |  |                            |            |
|   |  | Size   | Make                       | Balance    |
|   | R/H Front Tyre   | 275/40 R19   | MICHELIN                   | 5 mm       |
|   | L/H Front Tyre   | 275/40 R19   | MICHELIN                   | 5 mm       |
|   | R/H Rear Tyre  | 275/40 R19   | MICHELIN                   | 5 mm       |
|   | L/H Rear Tyre  | 275/40 R19   | MICHELIN                   | 5 mm       |
| <b>4. Description of Damages</b>  |  |  |                            |            |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |                            |            |
| <b>5. General Information</b>   |  |  |                            |            |
|   | Accident Date  | 21/04/2022   | Inspection Date            | 10/05/2022 |
|   | Survey held at   | CYCLE & CARRIAGE INDUSTRIES PL<br>188 PANDAN LOOP<br>SINGAPORE 128378<br>(MERCEDES-BENZ) |                            |            |
| <b>5a. Remarks</b>  |  |  |                            |            |
|   | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE MARKET VALUE IS S\$8,000.00(EST. AVERAGE)<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |  |                            |            |
| <b>5b. Estimate Days of Repair</b>  |  |  |                            |            |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 3 Working Days             |            |