

KIM CHWEE AUTO PTE LTD

Pg 1/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 22941

Date : 26.04.2022

Vehicle Num : SMT 4131U

Make/Model : BMW 328I A

Chassis/Engine no :

Accident Date : 23.04.2022

Claim No : 0422-22941

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear bumper reflector RH	\$ 47.50
1 pc	Rear bumper reflector RH	\$ 1,750.60
1 pc	Rear bumper diffuser	\$ 554.20
1 pc	Rear bumper reversing sensor (outer)	\$ 225.30
1 pc	Rear bumper reinforcement	\$ 570.20
1 pc	Rear bumper side retainer RH	\$ 86.00
1 pc	Taillamp LH	\$ 425.00
1 pc	Rear fender inner shield LH	\$ 181.10
1 pc	Rear top arm LH	\$ 280.90
1 pc	Rear lower arm LH	\$ 841.65
1 pc	Rear knuckle arm LH	\$ 1,365.50
1 pc	Rear wheel hub bearing LH	\$ 541.55
1 pc	Rear lower link arm LH	\$ 225.00
1 pc	Rear control arm LH	\$ 334.50
1 pc	Rear stay arm LH	\$ 272.50
List Item Total :		\$ 7,701.50
Discount 10 % :		\$ 770.15
		\$ 6,931.35

Special Nett Item :

1 pc	Rear sport rim RH	\$ 1,800.00
1 pc	Rear tyre RH	\$ 550.00
Special Nett Item :		\$ 2,350.00

KIM CHWEE AUTO PTE LTD

Pg 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 22941

Date : 26.04.2022

Vehicle Num : SMT 4131U

Make/Model : BMW 328I A

Chassis/Engine no :

Accident Date : 23.04.2022

Claim No : 0422-22941

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Labour Charge :</u>		
	To check wiring	\$ 80.00
	Remove and refix front & rear undercarriage	\$ 550.00
	Check wheel alignment	\$ 120.00
	Remove and refix rear interior trims to assist repair	\$ 180.00
	Panel beating , cut, weld, remove and replacing above parts	\$ 1,600.00
	To spray paint effected portion	\$ 1,400.00
	Labour Charge Total :	\$ 3,930.00
		\$ 13,211.35

KIM CHWEE AUTO PTE LTD