

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	1500.00 900
<u>2</u>	Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel) ?	1000.00 400
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	60.00 30
<u>4</u>	Remove and refit reverse sensor (Labour)	50.00 ✓
<u>5</u>	To conduct transfer of parts from old Bootlid to new Bootlid	150.00 60
940		
Labour Total :		2,760.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>1</u>	Sealant the m	50.00 +
<u>2</u>	Rear number plate me n	40.00 +
<u>3</u>	Rear Bumper Clip Set me	40.00 ✓
90		
Other Total :		130.00

Total : \$6,979.60
 Gst (7%) : \$488.57
GRAND TOTAL: \$7,468.17

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Advisor
 Ronnie Tan
 DID: 6844 1985 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Adrian Lj
 6/s 25/04/22.

04 Days

total: 2119.50
 4/s 1.7K