

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

26/04/2022 12:19

JOB-NO: 50114128

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7855T

TRANS: AUTO

CHASSIS: KMHCB51CVLU183592

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEKU388032

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,400.00	0.00	1,400.00	1000	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	180.00	0.00	180.00	30	Y	
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	280.00	0.00	280.00	30	Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	300.00	0.00	300.00	100	Y	
5 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	150.00	0.00	150.00	X	Y	
6 TO READJUST AND REALIGN HEADLAMP AIM	1.00	120.00	0.00	120.00	30	Y	
7 TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	1.00	180.00	0.00	180.00	100	Y	
8 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	50	Y	
9 TO CHECK AND REPAIR WIRE HARNESS	1.00	180.00	0.00	180.00	X	Y	
10 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	200	Y	
11 TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING	1.00	250.00	0.00	250.00	120	Y	
12 TO RESPRAY FRONT BUMPER MOULDING	1.00	250.00	0.00	250.00	50	Y	
13 TO RESPRAY FRONT BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	X	Y	
14 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	200	Y	
15 TO RESPRAY FRONT BONNET HINGE	1.00	250.00	0.00	250.00	X	Y	
16 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	
TOTAL:		4,800.00	0.00	4,800.00			

MATERIALS

1 FRONT BUMPER COVER	1.00	430.90	86.18	344.72	L	Y	
2 FRONT LH BUMPER RETAINER	1.00	28.00	5.60	22.40	L	Y	
3 FRONT LH BUMPER SIDE SUPPORT BRACKET	1.00	12.00	2.40	9.60	L	Y	
4 FRONT LH BUMPER MOULDING	1.00	93.00	18.60	74.40	L	Y	
5 FRONT LH FOG LAMP	1.00	642.50	128.50	514.00	L	Y	
6 FRONT LH BUMPER AIR CURTAIN DUCT	1.00	13.90	2.78	11.12	L	Y	
7 FRONT BUMPER ENERGY ABSORBER	1.00	86.90	17.38	69.52	L	Y	
8 FRONT BUMPER REINFORCEMENT	1.00	1,075.10	215.02	860.08	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
9 FRONT LH HEADLAMP <i>BR</i>	1.00	2,110.30	422.06	1,688.24	L	Y	
10 FRONT LH HEADLAMP COMPUTER	1.00	841.80	168.36	673.44	L	Y	
11 FRONT END MODULE CARRIER <i>BR</i>	1.00	949.30	189.86	759.44	L	Y	
12 FRONT LH FENDER PANEL <i>BR</i>	1.00	588.80	117.76	471.04	L	Y	
13 FRONT LH FENDER LINER <i>BR</i>	1.00	114.70	22.94	91.76	L	Y	
14 FRONT LH FENDER EMBLEM <i>X</i>	1.00	26.60	5.32	21.28	L	Y	
15 FRONT BUMPER LOWER LIP <i>X</i>	1.00	35.10	7.02	28.08	L	Y	
16 RADIATOR GRILLE <i>X</i>	1.00	1,409.10	281.82	1,127.28	L	Y	
17 RADIATOR GRILLE EMBLEM <i>X</i>	1.00	152.30	30.46	121.84	L	Y	
18 FRONT LH WHEEL RIM COVER <i>X</i>	1.00	346.40	69.28	277.12	L	Y	
19 FRONT BONNET <i>BR</i>	1.00	2,253.80	450.76	1,803.04	L	Y	
20 FRONT LH BONNET HINGE <i>X</i>	1.00	118.70	23.74	94.96	L	Y	
21 FRONT BUMPER CENTER UPPER MOULDING <i>X</i>	1.00	284.90 <i>cut</i>	56.98	227.92	L	Y	
22 FRONT BUMPER UNDERTRAY COVER <i>X</i>	1.00	469.40	93.88	375.52	L	Y	
23 FRONT LH PIEZO BUZZER <i>?</i>	1.00	70.40	14.08	56.32	L	Y	
24 A/C CONDENSER <i>X</i>	1.00	663.60	132.72	530.88	L	Y	
25 FRONT BUMPER LOWER GRILLE COVER <i>X</i>	1.00	186.90	37.38	149.52	L	Y	
26 FRONT BUMPER LOWER MOULDING <i>X</i>	1.00	44.00	8.80	35.20	L	Y	
27 RADIATOR GRILLE UPPER COVER <i>X</i>	1.00	48.30	9.66	38.64	L	Y	
28 FRONT LH ACTIVE UPPER AIR FLAP <i>X</i>	1.00	356.00	71.20	284.80	L	Y	
29 FRONT BUMPER LICENCE PLATE MOULDING <i>X</i>	1.00	158.60	31.72	126.88	L	Y	
30 FRONT BUMPER LOWER REINFORCEMENT <i>X</i>	1.00	85.10	17.02	68.08	L	Y	
31 FRONT BUMPER CLIP SET <i>MC</i>	1.00	65.00	0.00	30 65.00	S	Y	
32 FRONT BUMPER RIVET SET <i>MC</i>	1.00	60.00	0.00	10 60.00	S	Y	
33 RADIATOR COOLANT <i>MC</i>	1.00	120.00	0.00	30 120.00	S	Y	
34 FRONT FENDER LINER CLIP SET <i>MC</i>	1.00	60.00	0.00	15 60.00	S	Y	
35 FRONT BUMPER UNDERTRAY COVER CLIP <i>X</i>	1.00	55.00	0.00	55.00	S	Y	
36 FRONT BUMPER MOULDING CLIP SET <i>MC</i>	1.00	55.00	0.00	10 55.00	S	Y	
37 RADIATOR GRILLE CLIP SET <i>X</i>	1.00	55.00	0.00	55.00	S	Y	
TOTAL:		14,166.40	739.28	11,427.12			

TOTAL PARTS & LABOUR :

18,966.40

2,739.28

16,227.12

EXCESS/LOADING:\$ \$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$ \$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

mc PL
5 Lys
P/P
My Ref Sky
Part by Part
labow = \$ 2130.00
S/H = \$ 95.00
Parts = \$ 6017.68
Letst P = \$ 8242.68
Final Amt = \$ 8242.68