



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22003898/Uvy3h2	
			Date: 26/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKX 4418X	Veh. Inspected	SNB 9029H
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201412/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	26/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E250 (A)	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WDD2073472F104599	Colour	GREY/BLACK
	Odometer	180329 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35 ZR19	FALKEN	6 mm
	L/H Front Tyre	235/35 ZR19	FALKEN	6 mm
	R/H Rear Tyre	255/30 ZR19	FALKEN	6 mm
	L/H Rear Tyre	255/30 ZR19	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/04/2022	Inspection Date	27/04/2022
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	