

ASS. REC. BY: TGLm

REF:

CS/CT/22003899/Bgy3

Shiau Chan

ASSIGNMENT

From: _____ Date: 27/4/2022

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 737J

at Workshop m/s Bifrost Auto

of 85aki Bt, Ave 4 Premier # 01-49

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 55,000/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKM 737J Yr Regn: 5/11/2008

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Civic 1.8 C.C. 1799

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: R18A14002288

C/No: JHMFD16309S200252

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40/18

R: 225/40/18

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 24/4/2022 D.O.I. 27/4/2022

Survey held at Bifrost Auto

Des. of Damages ☒ Fr / ☒ Rear / ☒ S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range : 2,000/- - 3,000/-

Recommended CR: LS \$ 2450/-

6/11/22 @ finalised with the LS \$ 2000, 5 days. (Red \$ 8301.44, 80%)

MV 55,000/-

PV 20,957/-

NV 34,043/-

TGLm Wei

27/4/2022

Date/Time, File Pass to?

☐ : Preli. Report1) 12/4/2022 ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Rep. Format: MER-TP

Lump Sum / L.S. (\$)

2100

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	493I
Vehicle Details	
Vehicle No.:	SKM737J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A14002288
Chassis No.:	JHMF16309S200252
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$22,644.00
Original Registration Date:	05 Nov 2008
First Registration Date:	05 Nov 2008
Transfer Count:	3
Actual ARF Paid:	\$22,644.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Nov 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,121.00
COE Rebate Amount:	\$20,957.00
Total Rebate Amount:	\$20,957.00

The information contained herein is correct as at 26 Apr 2022

OK

MV 55,000/2
PV 20,957/2
NV 34,043/2

TG Lim
27/4/2022

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle number: SKM737J

Make & Model: Honda Civic

Chassis number: JHMFD16309S200252

Date of survey:_____

Name of surveyor: _____

Contacts:

2008

NECV
BRV
NDX
DDV
NDX

	\$	5,614.30
Parts less 20%	\$	1,122.86
Total	\$	4,491.44

$$\begin{array}{r} 1274.20 \\ 254.84 \\ \hline 1019.36 \end{array}$$

No.	Special Nett Items		Amount S\$
1	Front bumper (after -market)	1	\$ 800.00 1,250.00
2	Front bumper clips	1set	\$ 30.00 50.00
3	Front number plate	1	\$ 70.00
4	Brake fluid	1	\$ 60.00
5	LH front sport rim	1	\$ 400.00 1,280.00
6	LH front tyre	1	\$ 450.00
		Total:	\$ 3,160.00

DDV ✓
NEC ✓
} NDX
CUT ✓
NDX

Total:	\$	3,160.00
--------	----	----------

1230.00

No.	Labour and painting	Amount S\$

1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 400.00 1,000.00 ✓
2	Spray painting on affected areas and panels	\$ 400.00 1,000.00 ✓
3	Check wiring and lighting system on affected areas	\$ -80.00
4	Apply rust coating chemical on affected areas and panels	\$ -60.00
5	Refocus and adjust headlamps assy	\$ -60.00
6	Remove and replace front udnaercarriage parts to assist repair	\$ -450.00
7	Adjust and test drive wheel alignment system	\$ -100.00

✓
✓
} UNX

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____
 Total: \$ ~~800.00~~ 2,750.00

Spare Parts: \$ 4,491.44
 Special Nett: \$ 3,160.00
 Labour: \$ 2,750.00

Total Amount: \$ 10,401.44

Survey & Resurvey

27/4/2022 All external damages only

1430 hrs

Lump sum repair

Repair days 5

Parts 1019.36
 SN 1230.00
 Labour 800.00
 3049.36

LS 2100/2

TGim lin
 28/4/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____