



AP AUTOMOTIVE SERVICES PTE LTD
 REG. / GST REG. NO. 2020220001
 BLOCK 9000
 TAMPINES STREET 91 #01-202
 SINGAPORE 52840
 TEL 6784 4465
 FAX 6787 4888

ESTIMATION

DATE :
 VEHICLE : SME3938U
 MAKE / MODEL : MAZDA 3
 CHASSIS NO. :

No.	Description	Unit	Unit Price	Amount
PART REPLACEMENT				
	REAR DOOR LH 1048	1	\$ 1,270.40	\$ 1,270.40
	REAR DOOR HINGE LH	1	\$ 65.10	\$ 65.10
	REAR FENDER LH	1	\$ 1,174.20	\$ 1,174.20
	REAR FENDER INNER PANEL LH	1	\$ 428.00	\$ 428.00
	REAR FENDER COWLING LH	1	\$ 160.00	\$ 160.00
	REAR WINDSCREEN MOULDING	1	\$ 68.10	\$ 68.10
	REAR FENDER INNER COWLING LH	1	\$ 297.15	\$ 297.15
Total				\$ 3,462.95

Sub Total \$ 3,462.95

S/NETT ITEMS				
	REAR FENDER COWLING CLIPS (SET)	301PC 1	\$ 80.00	\$ 80.00
	REAR FENDER SEALANT	601CC 1	\$ 120.00	\$ 120.00
	REAR DOOR SEALANT	601CC 1	\$ 120.00	\$ 120.00
	REAR DOOR INNER TRIMBOARD CLIP	301CC 1	\$ 60.00	\$ 60.00
	REAR WINDSCREEN INNER TRIM CLIP (SET)	301CC 1	\$ 60.00	\$ 60.00
	REAR WINDSCREEN SEALANT	401CC 1	\$ 80.00	\$ 80.00
	TAIL LAMP PANEL SEALANT	XNN 1	\$ 80.00	\$ 80.00
	REAR WHEELHOUSE SEALANT	XNN 1	\$ 80.00	\$ 80.00
Total				\$ 680.00

LABOUR

	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00
	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
	REMOVE & REFIT INTERIOR UPHOLSTERY AND TRIMS TO FACILITATE REPAIRS	1	\$ 400.00	\$ 400.00
	TO APPLY RUST PROOFING	1	\$ 180.00	\$ 180.00
	TRANSFER DOOR MECHANISMS	1	\$ 80.00	\$ 80.00
	REMOVE AND REFIT REAR WINDOW GLASS	1	\$ 80.00	\$ 80.00
	REMOVE AND REFIT REAR WINDSCREEN GLASS	1	\$ 120.00	\$ 120.00
	CONDUCT WATER LEAKAGE TEST	1	\$ 80.00	\$ 80.00

Part Replacement Amount \$ 3,462.95

Thruvin 82235769
 26/4/22 1730
 L/S 5 days w/p

82235769 F: 2700 7682.95
 RD: 5



AP AUTOMOTIVE SERVICES PTE LTD
 ROC / GST REG NO : 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

ESTIMATION

DATE :
 VEHICLE : SME3938U
 MAKE / MODEL : MAZDA 3
 CHASIS NO. :

No.	Description	Unit	Unit Price	Amount
PART REPLACEMENT				
	REAR DOOR LH	1		
	REAR DOOR HINGE LH	1	\$ 1,270.40	\$ 1,270.40
	REAR FENDER LH	1	\$ 65.10	\$ 65.10
	REAR FENDER INNER PANEL LH	1	\$ 1,174.20	\$ 1,174.20
	REAR FENDER COWLING LH	1	\$ 428.00	\$ 428.00
	REAR WINDSCREEN MOULDING	1	\$ 160.00	\$ 160.00
	REAR FENDER INNER COWLING LH	1	\$ 68.10	\$ 68.10
		1	\$ 297.15	\$ 297.15
	Total			\$ 3,462.95

Sub Total \$ 3,462.95

S/NETT ITEMS				
	REAR FENDER COWLING CLIPS (SET)	301RCL 1	\$ 80.00	\$ 80.00
	REAR FENDER SEALANT	601RCL 1	\$ 120.00	\$ 120.00
	REAR DOOR SEALANT	601RCL 1	\$ 120.00	\$ 120.00
	REAR DOOR INNER TRIMBOARD CLIP	301RCL 1	\$ 60.00	\$ 60.00
	REAR WINDSCREEN INNER TRIM CLIP (SET)	301RCL 1	\$ 60.00	\$ 60.00
	REAR WINDSCREEN SEALANT	401RCL 1	\$ 80.00	\$ 80.00
	TAIL LAMP PANEL SEALANT	XNN 1	\$ 80.00	\$ 80.00
	REAR WHEELHOUSE SEALANT	XNN 1	\$ 80.00	\$ 80.00
	Total			\$ 680.00

LABOUR

	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00
	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
	REMOVE & REFIT INTERIOR UPHOLSTERY AND TRIMS TO FACILTATE REPAIRS	1	\$ 400.00	\$ 400.00
	TO APPLY RUST PROOFING	1	\$ 180.00	\$ 180.00
	TRANSFER DOOR MECHANISMS	1	\$ 80.00	\$ 80.00
	REMOVE AND REFIT REAR WINDOW GLASS	1	\$ 80.00	\$ 80.00
	REMOVE AND REFIT REAR WINDSCREEN GLASS	1	\$ 120.00	\$ 120.00
	CONDUCT WATER LEAKAGE TEST	1	\$ 80.00	\$ 80.00
	Part Replacement Amount			\$ 3,462.95

Thru van 82235769
 26/4/22 1730
 2/5 5 days wp

2/2/19 F: 2/2/19 2100
 RD: 5