

Massive Trading & Auto

BK 5038 #01-408 Ang Mo Kio Industrial Pk 2 Singapore 569541
Hp 91082728

Fax: 64816131

Chan Kin Leong
Bk 758 Woodlands Ave 6
#07-50
Singapore 730758

Not Authorized
L/Rng @ 3450/h
Proveny After Paint
3 days

Vehicle No: SJW 9521 E
Make/Model: BMW 318
Year: 2010

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s headlamp assy	1960.50	photo
1 pc	Front n/s headlamp lower bracket	62	photo
1 pc	Front bumper	1137	photo
1 pc	Front bumper reinforcement	?	photo
1 pc	Front n/s bumper side retainer	?	photo
1 pc	Front n/s fog lamp assy	?	photo
1 pc	Front n/s fog lamp garnish	66.55	photo
1 pc	Front n/s radiator grille	128	photo
1 pc	Front n/s radiator grille rubber	?	photo

CD	\$3,250.00	✓
CM	\$165.00	✓
BM	\$1,650.00	✓
R	\$550.00	X
DI	\$125.00	✓
MS CM	\$485.00	✓
ND	\$105.00	✓
ME	\$320.00	✓
SM	\$155.00	X
	\$6,805.00	
Less 10 %	\$680.50	
	\$6,124.50	

S. Nett Item

1 pc	Front no plate	✓
20 pcs	Rear bumper clip	

\$3.00	ND	\$40.00	✓
	SM	\$60.00	✓

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$600.00 30d

To putty and spray paint

\$600.00 350l

Check and reconnect wiring

\$45.00 20l

Total \$7,469.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: