

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6971A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER | TO REPAIR SEE LABOUR | 880.00 | - |
| 1 | FRONT BUMPER SIDE RETAINER (LHS) | NOT NECESSARY | 85.00 | - |
| 10 | FRONT BUMPER CLIP @\$4.00 | NOT NECESSARY | 40.00 | - |
| 1 | FRONT BUMPER FOGLAMP COVER (LHS) | NOT NECESSARY | 125.00 | - |
| 1 | FRONT FENDER (LHS) | TO REPAIR SEE LABOUR | 498.00 | - |
| 1 | FRONT HEADLAMP (LHS) | CUT | 1,075.00 | 1,075.00 |
| 10 | FRONT FENDER SPLASH SHIELD CLIP @\$4.00 | NOT NECESSARY | 40.00 | - |
| | LESS 20% DISCOUNT | | -548.60 | -215.00 |
| | | | 2,194.40 | 860.00 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT WHEEL HUP CAP (LHS) (SN) | NOT NECESSARY | 120.00 | - |
| 1 | FRONT TYRE (LHS) (SN) | NOT NECESSARY | 150.00 | - |
| 1 | FRONT RIM (LHS) (SN) | NOT NECESSARY | 250.00 | - |
| | | | 520.00 | - |
| | <u>LABOUR</u> | | | |
| | TO REMOVE AND REFOCUS FRONT HEADLAMP. | | 80.00 | 30.00 |
| | TO REMOVE & REPLACE LHS FRONT TYRE & LHS FRONT RIM & CONDUCT WHEEL BALANCING. | NOT NECESSARY | 120.00 | - |
| | TO KNOCK & PANEL BEAT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER (LHS). | | 600.00 | 200.00 |
| | TO CONDUCT WHEEL ALIGNMENT. | NOT NECESSARY | 150.00 | - |
| | TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA. | | 600.00 | 400.00 |
| | | | 1,550.00 | 630.00 |
| | GRAND TOTAL | | 4,264.40 | 1,490.00 |



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 1,200.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS/SMR22003903/Eny3e2



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator