



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22003904/Uny3m4 Date: 18/08/2022 Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKH 3126D	Veh. Inspected	SMZ 4273L	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D18282205	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	26/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	PEUGEOT 5008 (A)	c.c	1199	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	VF3MRHNSULS306701	Colour	WHITE	
Odometer	18859 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	MICHELIN	7 mm	
L/H Front Tyre	225/55 R18	MICHELIN	7 mm	
R/H Rear Tyre	225/55 R18	MICHELIN	7 mm	
L/H Rear Tyre	225/55 R18	MICHELIN	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/04/2022	Inspection Date	27/04/2022	
Survey held at	13 Kaki Bukit Road 4, Bartley Biz Centre, #01-24			
Repairer	ZOOM AUTOWERKS PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			20 Working Days	