



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

12 July 2022

REG NO.: SMZ 4273 L
MAKE/MODEL: PEUGEOT 5008

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Brake master pump <i>2000</i>	\$ 950.00
1	Rear bottom heat shield <i>Replaced</i>	\$ 250.00 X
		\$ 1,200.00
	Less 10%	\$ 120.00
		\$ 1,080.00

GRAND TOTAL :

\$ 1,080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-30717-30
102
27645.57
260
3820
31724.57