

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 Robinson Road
#09-01 S 068897

Attention : Motor Claim Department
Contact : 62972529 Fax No. : 63953768

Estimate : ES708316

Date : 25/04/2022
Vehicle Num. : SJY 448S
Make/Model : NISSAN QASHQAI
Chassis/Eng# :
Accident Date : 25/04/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	BONNET ✓ BT		750.00 ✓
2.	1 PC	O/S HEADLAMP ✓ CRA		450.00 ✓
3.	1 PC	FRONT BUMPER ✓ DE		480.00 ✓
4.	1 PC	O/S FRONT BUMPER SIDE RETAINER X NN		35.00
5.	1 PC	O/S FRONT FENDER ✓ BUC		450.00 ✓
6.	1 PC	O/S FRONT FENDER INNER SHIELD X NN		95.00
7.	1 PC	O/S FRONT WHEEL ARCH GARNISH ✓ CUT		320.00 ✓
8.	1 PC	O/S FRONT DOOR ✓ BT		✓ 1050 1,350.00
9.	1 PC	O/S FRONT DOOR STICKER ✓ NEC		45.00 ✓
10.	1 PC	O/S FRONT DOOR HINGE - TOP ✓ BT		70.00 ✓
11.	1 PC	O/S FRONT DOOR HINGE - BOTTOM X NN		70.00
12.	1 PC	O/S FRONT DOOR CHECKER ✓ BT		65.00 ✓
13.	1 PC	O/S FRONT DOOR INNER TRIM BOARD X NN		850.00
14.	1 PC	O/S WING MIRROR ✓ CUT		490.00 ✓
Total Parts Purchased S\$:				5,520.00 4170
10.00% Of The Above Parts S\$:				552.00
Based On Cost Plus S\$:				6,072.00 4587
SPECIAL NETT ITEMS :				
1.	1 PC	BONNET INSULATOR CLIP ✓ NEC		40.00 30

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 Robinson Road
#09-01 S 068897

Attention : Motor Claim Department
Contact : 62972529 Fax No. : 63953768

Estimate : ES708316

Date : 25/04/2022
Vehicle Num. : SJY 448S
Make/Model : NISSAN QASHQAI
Chassis/Eng# :
Accident Date : 25/04/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1 PC	FRONT BUMPER CLIP ✓ NEC		40.00 30
3.	1 PC	O/S FRONT FENDER INNER SHIELD CLIP ✓ NEC		40.00 20
4.	1 PC	O/S FRONT WHEEL ARCH GARNISH CLIPS ✓ NEC		40.00 20
5.	1 PC	O/S FRONT DOOR INNER TRIM BOARD CLIPS ✓ NEC		40.00 30
Special Nett Total S\$:				200.00
LABOUR :				
TO FOCUS HEADLAMP & WIRING				50.00 30
TO TRANSFER DOOR GLASS				120.00 80
TO TRANSFER DOOR MECHANISM				120.00
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA,				900.00 600
REPLACEMENT OF PARTS AND ALIGN THE SAME				
TO PUTTY AND SPRAY ACCIDENT DAMAGE AREA				1,000.00 900
Labour Total S\$:				2,190.00

6327

-20%: 5050


E. & O.E.

Total S\$: 8,462.00

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH



6 Days

Lumpsum repair

Not Authorised

Excess: TBA

After repair photos

Guo Qiang - LKK

82880282

27/04/2022