



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22000955/Vvy3e2-1	
			Date: 26/05/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 8887U	Veh. Inspected	SLR 930D
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025411	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	25/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZVW508062338	Colour	WHITE
	Odometer	401232 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FARROAD	5 mm
	L/H Front Tyre	195/65 R15	FARROAD	5 mm
	R/H Rear Tyre	195/65 R15	FARROAD	5 mm
	L/H Rear Tyre	195/65 R15	FARROAD	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2022	Inspection Date	27/01/2022
	Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	