

CHOON HOCK MOTOR TRADING CO

25 April 2022

*Not Authorized
L1 Pay @ 2500/-
Recovery After Paint
3 days*

ESTIMATE REPAIR BILL ON SLE 3058X HONDA VEZEL AUTO

1 pce front headlamp RH	V715-10	Mjcm	\$ 1,999.30	✓
1 pce front bumper assy.		Bj	\$ 466.20	✓
1 pce front bumper reinforcement		Bj	\$ 257.40	✓
1 pce front bumper fog light cover RH		Rd	\$ 25.90	✓
1 pce front bumper fog light RH		Mjcm	\$ 237.90	✓
1 pce front bumper lid RH		Bul Dis	\$ 212.70	✓
1 pce front fender arch garnish RH		Dis	\$ 150.60	✓
1 pce front retainer RH		CM	\$ 12.40	✓
			\$ 3,362.40	
		less 20%	\$ 672.48	
			\$ 2,689.92	

Labour

Wiring	\$ 60.00	2d
Panel beating	\$ 600.00	300d
Spray painting	\$ 600.00	40d
Total amount :	\$ 3,949.92	NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
Tel: (65) 64530778 Email: choonhockmotor@gmail.com