

9/5/2022

Lonpac Insurance Bhd
300 Beach Road
07, The Concourse #17-04
Singapore 199555
Attention: Motor Claims Department
Vehicle No.: SLP7728L

Dear Sirs,

ACCIDENT INVOLVING SLP7728L & SLT5019S ALONG PIE TOWARDS CHANGI BEFORE TOA PAYOH EXIT ON 23.04.2022 AT ABOUT 1645 HOURS.

We are the authorized workshop for **TEY SOON SENG**, owner of motor vehicle no. **SLP7728L**. We are instructed by the owner to claim damages against you/your insured in connection with a road traffic accident involving our client's vehicle registration number **SLP7728L** and vehicle registration number **SLT5019S** driven by your insured/you at the date and time as stated above.

We are instructed that the accident was caused by your insured's/your negligent driving and/or management of your insured/your vehicle. As a result of the accident, our client's vehicle was damaged and has been put to loss and expense. We are submitting these claims on behalf of owner/claimant for your considerations.

01) Lump Sum Repair		\$	6600	with 6 days
02) 6 Repair Days @ \$120/day		\$	720	
03) LTA Search Fees		\$	7.45	
04) Loss of Use/Rental 12 Days @ \$120/days	25/04/22-06/05/22	\$	1440	
Total:		\$	<u>8767.45</u>	

We enclosed herewith the supporting documents for the claim:-

- (a) Tax Invoice
- (b) Rental Tax Invoice
- (c) GIA report lodged by driver of SLP7728L

The demand herein is in respect of our client's claim for damages pertaining to his/her motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his/her personal injuries.

Please note that this demand is made without prejudice to our client's right to claim for his/her personal injury damages arising out of the same accident.

Yours Faithfully

Lim Chen Ya - 98073304



SATISFACTORY/DISCHARGE VOUCHER

Date: 09/05/2022

Policy No: 5112014753-02

Claim Ref. No: 21/22/22/VP05/025713 = SLT5019S & SLP7728L

To: LONPAC INSURANCE BHD

I/We hereby declare that the repair works done to my/our vehicle, bearing registration number SLP7728L which was involved in an accident on 07/05/2022 along PIE TOWARDS CHANGI BEFORE TPY EXIT, SINGAPORE has been completed by KY AUTO PTE LTD to my/our satisfaction. I/We agree that the payment amount paid to KY AUTO PTE LTD for the repairs shall be in full satisfaction and discharge of all claims which I/We may have in respect of our mentioned vehicle said policy number insured by NTUC INCOME INSURANCE CO-OPERATIVE LTD.

Signature of Owner:



Company Stamp (if applicable):

Policyholder's

Name: TEY SOON SENG

KY Auto Pte Ltd

25 Kaki Bukit Road 4
#05-23, Synergy
Singapore 417800
kyautosg@gmail.com
Company Registration No. 202028057R

**INVOICE**

BILL TO
LONPAC INSURANCE BHD
300, BEACH ROAD, 07 THE CONCOURSE, #17-04
SINGAPORE 199555

INVOICE 5163
DATE 09/05/2022
TERMS Due on receipt
DUE DATE 09/05/2022

CAR PLATE NO SLP7728L
CAR MODEL TOYOTA WISH

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
09/05/2022	SALES	LUMP SUM REPAIR + 6 REPAIR DAYS	1	7,320.00	7,320.00
	SALES	LOSS OF USE/RENTAL OF VEHICLE 12 DAYS @ \$120/DAY	12	120.00	1,440.00
	SALES	LTA SEARCH FEES	1	7.45	7.45

Thank you for your time and patience with us.

BALANCE DUE

S\$8,767.45

Transfer the amount to the business account below.

Kindly cross & make cheque payable to: "KY AUTO PTE. LTD."
or electronic transfer to Bank Account No. 601-305220-001
Bank OCBC (7339) OR UEN No. 202028057R
Penalty at 1.5% per month will be charge from due date.

LV Leasing Venture
BLK 963, HOUGANG AVE 9
#04-554, Singapore 530963 Tel: 88669092



INVOICE

KY AUTO PTE LTD
25 KAKI BUKIT ROAD 4
#05-23 S417800

DATE 09/05/2022
INVOICE NO. INV/9142/2022/002

CAR PLATE NO: SGT 9142 R
CAR MODEL HYUNDAI I30

ITEM	ACTIVITY	DESCRIPTION	AMOUNT
1.	RENTAL	RENTAL PERIOD 25/04/22 - 06/05/2022 (Replacement for SLP7728L)	\$1440.00

BALANCE DUE **S\$1440.00**

Transfer the amount to the business account below.

Kindly cross & make cheque payable to: "LV LEASING VENTURE." or electronic transfer to Bank Account No. 588-148965-001, Bank OCBC.

Alternative you can PayNow to our UEN 53390191W.

Penalty at 1.5% per month will be charge from due date.

4446 cecilia

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

W. of Alvin
her
2/5 \$6600
27/4/22
whatsapp Mr. Cg
Date: 25/04/2022
G.L.S.

M (65) 9807 3304 Mr. Yap

F (65)

Email: kvautosg@gmail.com

SLP7728L Toyota Wish — SLS 019S (Lampoc) ✓

Damaged Area: Rear Damaged

Parts / Material :

1	Tailgate	1.2/500	\$	1,295.60	—
2	Tailgate inner trim board	De/co.in	\$	455.20	2
3	Tailgate weatherstrip	7m	\$	381.80	—
4	Tailgate inner lock	22/chill	\$	412.60	—
2 pcs 5	Tailgate damper @ SGD 231.00	11	\$	462.00	X
6	Tailgate windscreen	moulding	\$	97.40	—
7	Tailgate logo	new	\$	98.60	—
8	Tailgate chrome moulding garnish	Old	\$	386.70	—
2 pcs 9	Tailgate lamp @ SGD 586.70 (LED - White)	one 425.10 x 2 = 850.20	\$	1,173.40	—
2 pcs 10	Taillamp assy @ SGD 780.90 (LED - White)	11	\$	1,561.80	X
2 pcs 11	Taillamp panel @ SGD 297.40	R	\$	594.80	X
12	Rear bumper	Dis	\$	856.40	—
2 pcs 13	Rear bumper side retainer @ SGD 120.20	3 set	\$	240.40	—
2 pcs 14	Rear bumper bracket @ SGD 68.20	NS	\$	136.40	—
2 pcs 15	Rear bumper reinforcement bracket	SGD 102.60	\$	205.20	X
16	Rear bumper tow cover	NS	\$	48.60	X
2 pcs 17	Rear bumper reflector @ SGD 145.70	one 85.10 x 2 = 170.20	\$	291.40	—
18	Rear spare tyre top board	11	\$	296.30	X
19	Rear spare tyre bracket	11	\$	455.70	X
20	Rear spare tyre panel	R	\$	937.10	X
21	Rear spare tyre foam N/S	NS	\$	298.70	X
22	Rear spare tyre Foam O/S	NS	\$	275.60	X
2 pcs 23	Rear fender inner trim garnish @ SGD 495.80	11	\$	991.60	X
2 pcs 24	Rear fender inner shield @ SGD 175.80	11	\$	351.60	X
25	Rear end panel inner	NS	\$	651.80	X
26	Rear end panel outer	3 set	\$	629.40	X
27	Rear end panel top garnish	7m	\$	298.60	—
28	Rear exhaust pipe	11	\$	920.40	—
29	Rear exhaust centre pipe	11	\$	146.80	—
2 pcs 30	Rear exhaust pipe mounting @ SGD 95.40	new 75.10 x 2 = 150.20	\$	190.80	—
31	Rear antenna sensor	113.50	\$	15,142.70	—
				Parts :	\$ 15,142.70
				Less Parts 25% :	\$ 3,785.67
				Total Parts :	\$ 11,357.02

Special Net Items :

1 set Rear bumper clips	nee	\$	60.00	80
Rear tailgate inner trimboard clips	nee	\$	50.00	40
Tailgate windscreen primer & cleaner	nee	\$	100.00	40
Tailgate windscreen sealant	nee	\$	80.00	40
Tailgate sealant	nee	\$	80.00	150
Rear fender inner trim garnish clips	17	\$	80.00	X
Rear end panel top garnish clips	17	\$	40.00	X
Rear end panel sealant	nee	\$	80.00	50
Rear floor panel sealant	17	\$	80.00	X
Rear floor panel insulation padding	11	\$	150.00	X
Rear number plate w/garnish	one	\$	55.00	40
Reverse sensor w/module	one	\$	280.00	200
Total S/N Parts :		\$	1,135.00	

Labour :

To Repair, Remove & Renew On Affected Rear Accident Areas @ SGD 300.00 per day	\$	1,500.00	850
To Putty, Spray Paint on Affected Rear Accident Areas @ SGD 300.00 per panel (Rear bumper, fenders, tailgate, end panel, floor panel)	\$	1,600.00	1100
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Remove & Transfer Tailgate Components to Facilitate Repairs	\$	120.00	60
To Remove & Install Rear Tailgate Glass to Facilitate Repairs	\$	150.00	120
To Remove & Install Rear Spare Tyre Compartment, Trims, Garnish to Facilitate Repairs	\$	150.00	80
To Remove, Align & Install Rear Exhaust Pipe	\$	150.00	60
To Install, Drill & Re-position Reverse Sensor	\$	150.00	50
To Rust Proof Affected Areas	\$	250.00	60
To Conduct Nano Coating on Affected Areas	\$	500.00	X
Total Labour :		\$	4,620.00

TOTAL PARTS :	\$	11,357.02
TOTAL SPECIAL NET ITEM:	\$	1,135.00
TOTAL LABOUR :	\$	4,620.00
TOTAL REPAIR COST :	\$	17,112.02

P-7160-90
 258
 P-5370-67
 S-N-510-00
 2-2400-00
 8280.67
 272
 6624.