

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0326/2022/JT
DATE : 22-Apr-22
WIP : 21091

Xiao Chui

\$10451.20

06 days.
#

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR OH CHUN AUN
ADDRESS : 2 SUFFOLK WALK
#09-02
SINGAPORE 307462
TELEPHONE : HP +65 98275980
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210013893
VEHICLE NO : SDY 886 G
MODEL CODE : AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR : 5/2/2021
ENGINE NO : CHZ C35839
CHASSIS NO : WAUZZZGA6LA002976
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Apr-22
PLACE OF ACCIDENT : AMBER GARDENS CAR PARK

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDY 886 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES AND RHS FRONT WING MIRROR ASSY.	S/N \$ 640.00	560 ✓
2	TO DISMANTLE AND RENEW RHS FRONT AND REAR DOORS. INSPECT B-PILLAR FOR DAMAGES. REPAIR RHS REAR FENDER. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	10001250
3	TO RESPRAY RHS FRONT AND REAR DOOR AND REAR RHS REAR FENDER.	\$ 2,700.00	2x550 = 1100 Mirror = 150 1800 ✓
4	TO RENEW RHS FRONT TYRE. CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,612.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDY 886 G - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT DOOR - RH <i>Distorted</i>	1	S 2,962.00	✓ 2369.60
2	GROMMET <i>new</i>	6	S 15.00	✓ X NN
3	FRONT DOOR CATCH - RH <i>Not New</i>	1	S 134.00	? X
4	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	S 98.00	x
5	FRONT DOOR HANDLE - RH <i>at</i>	1	S 398.00	✓ 318
6	FRONT DOOR SLIDE VALVE - RH <i>new</i>	1	S 25.00	x
7	FRONT DOOR HANDLE SENSOR - RH <i>new</i>	1	S 255.00	x
8	FRONT DOOR HANDLE CAP - RH <i>Not New</i>	1	S 62.00	x
9	FRONT DOOR UNDERLAY - RH	1	S 6.00	+
10	FRONT DOOR UNDERLAY END - RH <i>new</i>	1	S 7.00	+
11	FRONT DOOR MOUNTING BAR - RH	1	S 178.00	x
12	FRONT DOOR WINDOW APERTURE SEAL - RH OUTER <i>Not New</i>	1	S 151.00	x
13	FRONT DOOR COVER - RH <i>at</i>	1	S 270.00	✓ 216
14	WING MIRROR MOUNTING - RH <i>new</i>	1	S 1,130.00	x
15	WING MIRROR CAP - RH <i>Regis</i>	1	S 203.00	↓
SUB TOTAL SPARE PARTS		:	\$ 5,894.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED; REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

SURVEYOR COPY

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDY 886 G - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	REAR DOOR - RH <i>Distanted</i>	1	\$	2,962.00	✓ 2369.60
2	REAR DOOR OUTER SEAL - RH <i>see</i>	1	\$	151.00	✓ 120.40
3	BONDING AGENT <i>Neu</i>	1	\$	51.00	?
4	CLEANING SOLUTION <i>Neu</i>	1	\$	74.00	?
5	APPLICATOR <i>Neu</i>	1	\$	8.00	?
6	REAR DOOR CATCH - RH <i>Dysid</i>	1	\$	134.00	? 104 ✓
7	REAR DOOR HANDLE - RH <i>Neu</i>	1	\$	398.00	+
8	REAR DOOR WINDOW APERTURE SEAL - RH OUTER <i>MP</i>	1	\$	151.00	✓
9	REAR DOOR COVER - RH <i>ut</i>	1	\$	238.00	✓ 190.40
10	REAR WHEEL ARCH COVER - RH <i>ut</i>	1	\$	180.00	✓ 143.60
11	DUNLOP TYRE <i>see</i>	S/N	TBC		+
12	SUNDRRIES <i>Neu</i>		\$	400.00	? 17.60 ✓
TOTAL SPARE PARTS (FRONT & REAR)		:	\$	10,641.00	
TOTAL LABOUR CHARGES		:	\$	6,612.00	
GRAND TOTAL		:	\$	17,253.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adnan
25/04/22

Not Authorized, 05 Days. 06 Days.
S.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: