

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001891/KPA3Q2-1**Date:** 21/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900008677
Claimant Vehicle No :	SBM2882R	Insured Vehicle No :	SKQ4448X
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	4514770867SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBM2882R		
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Engine No:	4G18JQ6754
Reg. Date:	16/06/2008 (Man. Year: 2008)	Chassis No:	JMYSNCS3A8U004241
Colour:	Black	Odometer:	435949 km
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,751.00	2,812.75	938.25	25.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,990.00	250.00	11.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,991.00	4,802.75	1,188.25	19.83
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	5,991.00	3,850.00	2,141.00	35.74
+ GST 7.00/7.00% (S\$)	419.37	269.50	149.87	35.74
Nett Amount (S\$)	6,410.37	4,119.50	2,290.87	35.74
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,826.99		

INSPECTION

Date of Assignment:	08/02/2021	
Date Inspected:	02/03/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	988.00 FN	*895.00 FN
2	1		*FRONT RH DOOR OUTER CHROME MOULDING	Necessary	96.00 FN	*96.00 FN
3	1		*REAR RH DOOR	Bent	961.00 FN	*745.00 FN
4	1		*REAR RH DOOR OUTER CHROME MOULDING	Necessary	96.00 FN	*96.00 FN
5	1		*REAR RH DOOR TOP HINGE	Repair	52.00 FN	*- FN
6	1		*REAR RH DOOR CHECKER	Serviceable	61.00 FN	*- FN
7	1		*REAR RH DOOR POWER WINDOW MOTOR	Serviceable	385.00 FN	*- FN
8	1		*REAR RH DOOR POWER WINDOW MOTOR REGULATOR	Distorted	121.00 FN	*121.00 FN
9	1		*REAR RH FENDER	Bent	1,018.00 FN	*782.50 FN
10	1		*REAR WINDSCREEN GLASS MOULDING TOP	Necessary	49.00 FN	*49.00 FN
11	1		*REAR WINDSCREEN GLASS MOULDING LOWER	Necessary	163.00 FN	*163.00 FN
12	1		*UNIT REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*SET DOOR VISOR	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	4,150.00	3,107.50
- Nett Item Discount on N Items 10.00/10.00% (\$)	399.00	294.75
Total Parts (\$)	3,751.00	2,812.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS ,REAR BOOT & ATTACHMENTS TAILLAMPS ,BOTH RH DOORS & ATTACHMENTS TO CUT ,WELD & RENEW REAR RH FENDER ,KNOCKING & REPAIR RH DOOR PILLAR ,REAR END PANEL & REALIGN THE SAME	New	900.00	800.00
3	PUTTY & RESPRAY REAR BUMPER & LOWER SKIRT ,RH SIDE SKIRT ,BOTH RH DOORS ,PILLARS ,REAR RH FENDER ,REAR END PANEL & ALL AFFECTED AREAS	New	950.00	800.00
4	REMOVE & REFIX RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	New	100.00	100.00
5	REMOVE & REFIX REAR SEAT ,CARPET GARNISH TO FACILITATE REPAIR	New	100.00	100.00
6	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (\$\$)			2,240.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >