

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2190179/WS
Date: 02 Mar 2021
Policy No: 5029051675-12 DC
Veh Reg No: SBM2882R
Make/Model: MITSUBISHI LANCER
1.6M
Chassis No: JMYSNCS3A86004241
Engine No: 4G18JQ6754
Reg. Date: 16/06/2008

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 07/02/2021
TP Veh Reg No: SKQ4448X

Not Notarise
1 Day 83850k
Person After Paint 7 days

Estimate Repair Cost to Vehicle No :SBM2882R

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 FRONT RH DOOR <i>895</i>	988.00	1 PC	<i>R</i> 988.00	<i>✓</i>
2 FRONT RH DOOR OUTER CHROME MOULDING	96.00	1 PC	<i>m</i> 96.00	<i>✓</i>
3 REAR RH DOOR <i>745</i>	961.00	1 PC	<i>R</i> 961.00	<i>✓</i>
4 REAR RH DOOR OUTER CHROME MOULDING	96.00	1 PC	<i>m</i> 96.00	<i>✓</i>
5 REAR RH DOOR TOP HINGE	52.00	1 PC	<i>n</i> 52.00	<i>x</i>
6 REAR RH DOOR CHECKER	61.00	1 PC	<i>n</i> 61.00	<i>x</i>
7 REAR RH DOOR POWER WINDOW MOTOR	385.00	1 PC	<i>n</i> 385.00	<i>x</i>
8 REAR RH DOOR POWER WINDOW MOTOR REGULATOR	121.00	1 PC	<i>n</i> 121.00	<i>✓</i>
9 REAR RH FENDER <i>782.50</i>	1,018.00	1 PC	<i>R</i> 1,018.00	<i>✓</i>
10 REAR WINDSCREEN GLASS MOULDING TOP	49.00	1 PC	<i>m</i> 49.00	<i>✓</i>
11 REAR WINDSCREEN GLASS MOULDING LOWER	163.00	1 PC	<i>m</i> 163.00	<i>✓</i>
			3,990.00	
		Less 10%	399.00	3,591.00
Special Net				
12 REAR WINDSCREEN GLASS SEALANT	40.00	1 UNIT	<i>m</i> 40.00	<i>✓</i>
13 DOOR VISOR	120.00	1 SET	<i>m</i> 120.00	<i>✓</i>
			160.00	160.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	<i>✓</i>
15 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, REAR BOOT & ATTACHMENTS, TAILLAMPS, BOTH RH DOORS & ATTACHMENTS, TO CUT, WELD & RENEW REAR RH FENDER, KNOCKING & REPAIR RH DOOR PILLAR, REAR END PANEL & REALIGN THE SAME	900.00	1 LA	900.00	<i>800</i>
16 PUTTY & RESPRAY REAR BUMPER & LOWER SKIRT, RH SIDE SKIRT, BOTH RH DOORS & PILLARS, REAR RH FENDER, REAR END PANEL & ALL AFFECTED AREAS	950.00	1 LA	950.00	<i>800</i>
17 REMOVE & REFIX RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	100.00	1 LA	100.00	<i>✓</i>
18 REMOVE & REFIX REAR SEAT, CARPET, GARNISH TO FACILITATE REPAIR	100.00	1 LA	100.00	<i>✓</i>
19 RUSTPROOFING	90.00	1 LA	90.00	<i>✓</i>
			2,240.00	2,240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: