

HS AUTOMOTIVES

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOMHUB #02-25 SINGAPORE 417921.
TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM
ROC: 201907812C

Vehicle No : SKW 9831R
Make/Model : AUDI A3
CHASSIS NO : WAUZZZ8V001A 043725

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	

WORK SHOP REPAIRER ESTIMATE

Date: _____

Estimate cost of repair to the above mentioned

NO.	QTY	List Items	MARKING	UNIT	\$	AMOUNT (\$)	REMARKS
1	1	REAR TAIL GATE	1870	*	\$ -	\$ 1999.60	DT
2	1	REAR TAIL GATE LOGO (A3)			\$ -	\$ 160.77	1PC
3	1	REAR TAIL GATE LOGO (TFSI)			\$ -	\$ 149.79	1PC
4	1	REAR TAIL GATE LOGO (AUDI COUNTRY)			\$ -	\$ 166.70	1PC
5	2	REAR TAIL GATE INNER TRIM BOARD			\$ -	\$ 600.33	7. Cut
6	2	REAR TAIL GATE REFLECTOR (K) XSUC	1PC		\$ 999.70	\$ 1999.40	1PC
7	2	REAR TAIL GATE DAMPER K/R			\$ -	\$ XSUC	1PC
8	1	REAR TAIL GATE WEATHER STRIP 300			\$ -	\$ 400.67	1PC
9	2	REAR TAIL GATE N/PLATE LAMP			\$ 132.40	\$ 266.80	XSUC
10	1	REAR TAIL GATE LOCK			\$ -	\$ 379.45	XSUC
11	1	REAR TAIL GATE INNER TRIM BOARD CLIP	8/N		\$ -	\$ 76.00	30NOC
12	1	REAR WINDSHIELD STACAN	8/N		\$ -	\$ 120.00	60NOC
13	1	LH REAR FENDER			\$ -	\$ 1999.70	Xr/1PC
14	1	LH REAR FENDER INNER SHIELD			\$ -	\$ 379.35	7. XSUC
15	1	LH REAR FENDER INNER SHIELD CLIP S/W			\$ -	\$ 76.00	30NOC
16	1	LH REAR FENDER TAIL LAMP 50097			\$ -	\$ 900.97	1PC
17	1	REAR BUMPER			\$ -	\$ 1488.90	1PC
18	1	REAR BUMPER CLIP	8/N		\$ -	\$ 79.00	30NOC
19	2	REAR BUMPER RETAINER K/R			\$ 60.67	\$ 121.34	1PC
20	4	REAR BUMPER REVERSE SENSOR ORIGINAL	2PC		\$ 23.75	\$ 95.00	1PC

REMARKS

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	

24312.43

HS AUTOMOTIVES

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No : QKW 4831R
 Make/Model : ACU 1 A3
 CHASSIS NO : WAL22281081A023725

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	

WORK SHOP REPAIRER ESTIMATE

Date: _____

Estimate cost of repair to the above mentioned

NO.	QTY	List Items	MARKING	UNIT	\$	AMOUNT (\$S)	REMARKS
1	1	RRAR BUMPER RIVETS BAMPOR WIRE HARDWARES.		\$	-	\$ 273.46	X50C
2	1	RRAR BONDING REINFORCEMENT.		\$	-	\$ 600.60	7.1/NT
3	1	RRAR END BAZEL.		\$	-	\$ 1300.75	7.1/NT
4	1	RRAR END BAZEL TOP GARNISH		\$	-	\$ 146.35	X50C
5	1	RRAR END BAZEL TOP GARNISH CLIP	SN	\$	-	\$ 73.00	300pc
6	1	RRAR EXHAUST PIPE	SN 300	\$	73	\$ 1800.99	7.1/NT
7	2	RRAR EXHAUST PIPE MOUNTING		\$	73.20	\$ 146.40	X50C
8				\$	-	\$ -	
9		2/1		\$	-	\$ -	
10	1	RRAR LOWER BUMPER		\$	-	\$ 288.96	1/4t
11	1	RRAR BUMPER TOP BRACKET.		\$	-	\$ 273.46	1/4t
12	1	RRAR FENDER AIR VENT		\$	-	\$ 97.30	1/4t
13	1	RRAR FENDER GLASS BEACON		\$	60	\$ 120.00	1/4t
14				\$	-	\$ -	
15				\$	-	\$ -	
16				\$	-	\$ -	
17				\$	-	\$ -	
18				\$	-	\$ -	
19				\$	-	\$ -	
20				\$	-	\$ -	

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	

4341.55
779.71

HS AUTOMOTIVE SERVICES

Blk 2 Kaki Bukit Ave 2 @ Kaki Bukit Autohub #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 53081191W

Vehicle No: 8KW 7831R

Make/Model: AUDI A3

CHASSIS NO: NAUZZZ8V061A003705

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

Date: _____

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

		MARKING	UNIT \$	AMOUNT (\$\$)
1	PAINT B&T	800	200	1600
2				
3	RESPRAY PAINT.	1000 B&T	600	1600
4				
5	TO TRANSFER COMPONENT		50	180
6				
7	TO REMOVE AND REFIX REAR LIGHTING.		90	250
8				
9	TO REMOVE AND REFIX REAR WINDSCREEN		120	180
10				
11	TO CHECK WIRING		30	100
12				
13	TO INSTALL REAR REVERSE SENSOR		30	120
14				
15	RUST PROOF		30	120
16				
17	TO REMOVE AND REFIX FENDER GLASS.		60	180
18				
19				
20				

REMARKS:

NO OF DAYS:	7 days
AGREED FIGURE/LUMP SUM:	
SURVEYOR NAME:	Thavan
EMAIL ADD:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is a CONTACT: 8225 5209

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

F: 9500

RP-7

30763.69