

FASTTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay.
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

VEHICLE No: GBB 528K

NETT ITEM

1PC	FRONT WINDSCREEN	1095.30	one	\$1,488.20	
1PC	FRONT WINDSCREEN MOULDING		new	\$128.20	
1PC	FRONT WIPER PANEL	387.20	but/used	\$445.20	
1PC	FRONT PANEL	1412.70	do/used	\$1,915.20	
1PC	FRONT PANEL 'CABSTAR' EMBLEM		new	\$45.80	
1PC	FRONT GRILLE		11	\$578.60	X
1PC	FRONT GRILLE LOGO		11	\$68.00	X
1PC	HEADLAMP N/S	518.50	one	\$800.00	
1PC	HEADLAMP TOP GARNISH N/S		3/20	\$366.80	
1PC	HEADLAMP LOWER GARNISH N/S	68.50	1/1	\$121.00	
1PC	FRONT BUMPER	454	dis	\$945.00	
1PC	FRONT BUMPER BEAM		2	\$605.00	X
2PCS	FRONT CORNER PANELS @\$389.90	436	1/1 20/5/11	\$779.80	1/2
1PC	AIR CON BLOWER		11	\$1,665.00	X
1PC	HEATER UNIT		11	\$2,820.00	X
1PC	FRONT MIRROR BRACKET ASSY N/S	450.50	but	\$688.50	
1PC	FRONT MIRROR ROUND N/S	98.50	3/20	\$145.00	
1PC	FRONT MIRROR RECTANGLE N/S	183.20	3/20	\$245.00	
1PC	FRONT WINDSCREEN SEALANT		new	\$45.00	40 S/N
1PC	FRONT PANEL SEALANT		new	\$50.00	
1PC	FRONT DOOR OUTER PILLAR N/S		2	\$899.10	X
1PC	FRONT DOOR N/S		2	\$1,655.20	X
				\$16,499.60.	

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$60.00	30
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$150.00	100
TO DISMANTLE & REFIX FRONT DASHBOARD	\$380.00	200
TO DISMANTLE & REPLACED AIR CON BLOWER	\$180.00	X
TO REFIX AIR CON GAS	\$150.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,180.00	800
TO PUTTY & SPRAY PAINTING	\$1,100.00	800
TOTAL		\$19,749.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 6134.1
102
P- 5520.69
S.N - 40
L- 1950
751069