

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406

Singapore 539195

H/P : 9299 6636 Fax : 6285 7054

Date : 27-Apr-22

Estimated repair cost of SJW 2870 C MAZDA 3

<u>Qty</u>	<u>Description</u>	<u>Amt S(\$)</u>
	<u>List Items</u>	
1	Front headlamp -RH <i>cm</i> ✓	\$ 2,254.00
1	Front grille <i>de</i> ✓	\$ 581.00
1	Front bumper <i>de</i> ✓	\$ 1,031.70
1	Front bumper lower grille <i>xnn</i>	\$ 128.30 X
1	Front bumper reinforcement <i>? xnn</i>	\$ 568.40 X
1	Front bumper logo <i>nn</i> ✓	\$ 85.00
<i>2/1pc</i>	Front bumper side retainers <i>RH-? cut</i> ✓	\$ 85.00 42.50
1	Front bumper side grille <i>? cm</i> ✓	\$ 315.00
1	Front bumper rubber seal <i>nn</i> ✓	\$ 112.00
1	Rear windscreen moulding <i>nn</i> ✓	\$ 98.90
1	Rear boot lid <i>bt</i> ✓	\$ 972.00
2	Rear boot hinges <i>bt</i> ✓	\$ 280.80
1	Rear boot inner trim <i>de</i> ✓	\$ 172.90
<i>2/1pc</i>	Rear boot lamps <i>RH-cm / LH-? xnn</i>	\$ 492.00 246
1	Rear boot inner lock <i>bt</i> ✓	\$ 221.80
1	Rear boot logo <i>nn</i> ✓	\$ 69.00
1	Rear boot rubber <i>nn</i> ✓	\$ 120.00
1	Rear boot "MAZDA 3" emblem <i>nn</i> ✓	\$ 55.50
<i>2/1pc</i>	Rear taillamps <i>cm / RH-cm / LH-? xnn</i>	\$ 1,699.20 845.60
1	Rear end panel <i>st</i> ✓	\$ 624.70
1	Rear end panel inner garnish <i>de</i> ✓	\$ 212.50
1	Rear bumper <i>nn</i> ✓	\$ 998.00
2	Rear bumper brackets <i>nn</i> ✓	\$ 67.00
2	Rear bumper reflectors <i>cm</i> ✓	\$ 124.00
1	Rear bumper reinforcement <i>bt</i> ✓	\$ 547.00
2	Rear bumper side retainers <i>nn</i> ✓	\$ 77.20
1	Rear floor board <i>xnn</i>	\$ 193.90 X
1	Rear floor panel <i>nn repair</i>	\$ 2,114.20 XR
<i>2/1pc</i>	Rear fenders <i>LH-X / RH-bt</i>	\$ 2,182.00 1091
2	Rear fender inner shields <i>xnn</i>	\$ 147.00 X
<i>2/1pc</i>	Rear fender inner trims <i>LH-X / RH-cd</i> ✓	\$ 468.80 234.40
		<i>11483.50</i>
		\$ 17,098.80
	Less 20% <i>20%</i>	\$ 3,419.76
		<i>9186.80</i>
		\$ 13,679.04

Special Nett Items

- | | | |
|---|-------------------------------|-----------|
| 1 | Front bumper clip (1 set) | <i>ms</i> |
| 1 | Rear windscreen sealant | <i>ms</i> |
| 1 | Rear bumper clip (1 set) | <i>ms</i> |
| 1 | Rear number plate with holder | <i>ms</i> |
| 1 | Rear reverse sensor (1 set) | <i>ms</i> |

335

\$	50.00 30
\$	80.00 40
\$	50.00 30
\$	50.00 35
\$	350.00 200
\$	580.00

S/N

LABOUR CHARGES

- | | |
|----|--|
| 1 | To check wiring and reset headlamps focusing. |
| 2 | To remove, replaced damaged lamps and check up rear wiring. |
| 3 | To remove and refit inner garnishes. |
| 4 | To remove and refit rear reverse sensor. |
| 5 | To transfer boot lid mechanism and wiring assembly. |
| 6 | To remove and refit fuel tank assembly with all attachments. |
| 7 | To remove and refit rear windscreen glass. |
| 8 | To apply undercoating. |
| 9 | Panel beating. |
| 10 | To re-spray painting on the affected areas. |

3090

\$	X 80.00 200 ⁿⁿ X
\$	80.00 30
\$	150.00 60
\$	150.00 60
\$	80.00 60
\$	150.00 60
\$	180.00 120
\$	200.00 100
\$	2,000.00 1400
\$	1,800.00 1200
\$	4,870.00

Grand Total :

\$ 19,129.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasmi
Hr 900 10068
12 days
4/5
27/04/22 @ 1240
Resy after repair

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406
Singapore 539195
H/P : 9299 6636 Fax : 6285 7054

Date : 29-Apr-22

Supplementary estimated repair cost of SJW 2870 C MAZDA 3

<u>Qty</u>	<u>Description</u>	<u>Amt S(\$)</u>
	<u>List Items</u>	
1	Front bumper inner sponge <i>cm</i>	\$ 185.00
1	Front support panel <i>cm</i>	\$ 855.00
		\$ 1,040.00
	Less 20%	\$ 208.00
		\$ 832.00

832

S/N LABOUR CHARGES

1 To remove, refit air-con condenser, refill gas & conduct leakage test.

100

\$ ~~100~~ 180.00

\$ 180.00

9186.80
335.00
3090.00
832.00
100.00

13543.80

Grand Total :

\$ 1,012.00

20%
10,835.04
L/S - \$10,800
