



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/07/2022

Attn: The Motor Claims Department

Your Insured veh no : YP3183E

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

Dear Sir / Madam

WITHOUT PREJUDICE

(By Email Only)

Final Cost of repair bill for Toyota Hiace GBC8524M And YP3183E on 23/04/2022 at 13:25 PM.

To Supply :-

Total Lumpsum As Of Repair Costs Recommended By Surveyor And

Agreed By Ourselves : \$ 1,900.00

GST 7% \$ 133.00

\$ 2,033.00





凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/07/2022

Attn: The Motor Claims Department

Your Insured veh no : SCL9119J

Allianz SE, Singapore Branch

79 Robinson Road, #09-01

Asia Square Tower 1 Singapore 068897

claims@allianz.com.sg

WITHOUT PREJUDICE

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE - Toyota Hiace GBC8524M And YP3183E on 23/04/2022 at 13:25 PM.

We have been authorised by Gyoseki fashion Pte Ltd, the owner of vehicle claim against the party/ parties responsible for the damages arising from number GBC8524M, to the above mentioned accident.

Our records show that you are the insurers of vehicle number (YP3183E) at the material time of the accident with the driver of our client's vehicle, (Gyoseki fashion Pte Ltd).

As a result of the accident caused by your insured driver's negligent driving and/or management of your insured's vehicle number (YP3183E), our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 2,033.00
(2) Loss of use 3days X 80	\$ 240.00
(3) PIR 2days	\$ 160.00
(4) LTA Fee	\$ 7.45
	<u>\$2,440.45</u>



A cope of each of the following supporting documents is enclosed:

- (a) Final repair bill
- (b) GIA report with sketch plan of (our client's veh number)
- (c) LTA Search