



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/04/2022

Attn: The Motor Claims Department
Your Insured veh no : YP3183E
AIG ASIA PACIFIC INSURANCE PTE LTD.
78 Shenton Way
07-16 Chartis Building
Singapore 079120
Dear Sir / Madam

WITHOUT PREJUDICE

(By Email Only)

Estimated Cost of repair bill for Toyota Hiace GBC8524M And YP3183E on 23/04/2022 at 13:25 PM.
To Supply :-

1pc	Rear Boot Cover	Dented	2259.90	1,765.00	✓
1pc	"Toyota" Logo	3m		55.10	✓
1pc	"Hiace" Logo		1694.92	65.10	✓
1pc	"Logo"	3m		78.10	✓
1pc	70km/h Sticker		S.N: 10.	31.10	✓ 10(SN)
2pcs	Boot Cover Hinge	near Bent	2pcs X S148.30	296.60	✓
1pc	Boot Cover Lock Inner	men		213.40	✓
				2,504.40	
Less 10%				- 250.44	
				2,253.96	

1pc	Rear Windscreen Glass Seal	3m	115	55.00	S/Nett ✓
1pc	Rear Windscreen Sealant			85.00	S/Nett → 60

To dismantle & replace damage parts, panel beat where necessary
To putty, apply primer & spray paint on the affected portion.
To remove and refix rear windscreen glass
To check wiring functions.

550.00	200
580.00	200
150.00	120
100.00	30
3,773.96	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 2369.92
L/S: 1.9K

Adrian Lj
L/S 28/04/22
03 days