

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003924/UVY3Q2**Date:** 13/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00034762200	
Claimant Vehicle No :	SLV3168Y	Insured Vehicle No :	GY3653G	
Date of Loss:	20/04/2022	Nature of Claim:	TP	Claim No: SNM22D202689/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3168Y		Engine No:	PY21027554
Make & Model:	MAZDA 6, 2.0 (A)		Chassis No:	JM6GL103100131782
Reg. Date:	27/12/2017 (Man. Year: 2017)		Odometer:	82568 km
Colour:	Red			
Engine Capacity:	2488 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,494.50	1,755.30	739.20	29.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	2,440.00	900.00	26.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,834.50	4,195.30	1,639.20	28.09
+ GST 7.00/7.00% (\$\$)	408.42	293.67	114.75	28.10
Nett Amount (\$\$)	6,242.92	4,488.97	1,753.95	28.10

INSPECTION

Date of Assignment:	27/04/2022		
Date Inspected:	28/04/2022	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3168Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,230.30 F	*1,230.30 F
2	2		*RETAINER S.S ULTRASONIC CENTER	Necessary	22.60 F	*22.60 F
3	2		*TAPE PROTECTOR	Necessary	17.20 F	*17.20 F
4	2		*SENSOR ULTRASONIC CENTER	Shorted	401.00 F	*401.00 F
5	1		*CORD SHORT REAR BUMPER	Not Necessary	125.00 F	*- F
6	1		*BRACKET CENTER REAR BUMPER	Not Necessary	5.40 F	*- F
7	4		*GROMMET ,SCREW	Necessary	10.80 F	*10.80 F
8	1		*REINFORCEMENT REAR	Not Necessary	511.00 F	*- F
9	1		*COVER TOWING LH REAR	Not Necessary	23.90 F	*- F
10	1		*COVER TOWING RH REAR	Not Necessary	23.90 F	*- F
11	6		*FASTENER	Necessary	18.00 F	*18.00 F
12	1		*GASKET RH TAIL LAMP	Necessary	27.70 F	*27.70 F
13	1		*GASKET LH TAIL LAMP	Necessary	27.70 F	*27.70 F
14	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,494.50	1,755.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER	New	800.00	660.00
2	TO RESPRAY REAR BUMPER	New	700.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	250.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	150.00
6	SPRAY TAILGATE	New	630.00	630.00
Gross Labour Cost (\$)			3,340.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >