

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chee So Chow

Date: 28 Sep 2022

Preliminary Advice

Vehicle No	: GBK1245Y	Accident Date	: 09/04/2022
Make	: RENAULT KANGOO	Policy No.	: DMCVSNW00150822101
Assignment Date	: 27/04/2022	Excess	: S\$450.00
Date of Inspection	: 28/04/2022	Est. Duration of Repair	: 16
Inspection At	: AUTO INSURE PTE LTD (HQ) (WOODLANDS) 6 MARSILING LANE SINGAPORE 739145		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 53,985.20	(Estimate \$32,615.20 + Supplementary \$21,370.00)
Revised Amount	:S\$ 41,310.20	
Check Items (Estimated)	:S\$ 9,258.00	
Total	:S\$ 50,568.20	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	18,147.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,853.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT MORE
THAN \$48,000.00 ON LUMP SUM BASIS.