

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200128
Date: 26 Apr 2022
Veh Reg No: SLV8501K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81200787
Reg. Date: 18/01/2018
Your Ref No: SMF2751S

Claim Type: Third Party
Accident Date: 21/04/2022
TP Veh Reg No: SMF2751S

Estimate Repair Cost to Vehicle No :SLV8501K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	1,293.00	
2	1 PC BOOT LID LOGO	68.50	
3	1 PC BOOT LID "SHUTTLE" EMBLEM	80.10	
4	2 PCS BOOT LID HINGE	136.00	
5	2 PCS BOOT LID SHOCK ABSORBER	390.00	
6	1 PC BOOT LID CHROME	332.70	
7	1 PC BOOT LID LAMP RH	495.00	
8	1 PC BOOT LID LAMP LH	495.00	
9	1 PC BOOT LID GARNISH	383.00	
10	1 PC REAR WINDSCREEN GLASS	1,310.00	
11	1 PC REAR WINDSCREEN RUBBER	120.60	
12	1 PC REAR WINDSCREEN RH GARNISH	202.10	
13	1 PC REAR WINDSCREEN LH GARNISH	202.10	
14	1 PC REAR WIPER MOTOR	698.80	
15	1 PC REAR WIPER ARM	95.50	
16	1 PC REAR WIPER BLADE	66.50	
17	1 PC REAR BOOT BALANCER	192.70	
18	1 PC BOOT LID LOCK	259.00	
19	1 PC BOOT LID LOCK CHECKER	32.80	
20	1 PC BOOT LID RUBBER	260.60	
21	2 PCS BOOTLID STOPPER	16.00	
22	1 PC BOOT LID HOLDING HANDLE	59.80	
23	1 PC BOOTLID TRIM	360.80	
24	1 PC REAR FENDER LH	1,210.90	
25	1 PC REAR FENDER GLASS LH	578.60	
26	1 PC REAR FENDER TRIM LH	589.60	
27	1 PC REAR FENDER TOP TRIM LH	404.30	
28	1 PC REAR FENDER TRIM RH	589.60	
29	1 PC TAIL LAMP - RH	560.50	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200128
Date: 26 Apr 2022
Veh Reg No: SLV8501K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81200787
Reg. Date: 18/01/2018
Your Ref No: SMF2751S

Claim Type: Third Party
Accident Date: 21/04/2022
TP Veh Reg No: SMF2751S

Estimate Repair Cost to Vehicle No :SLV8501K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC TAIL LAMP OUTER PANEL RH	466.70	
31	1 PC TAIL LAMP INNER PANEL RH	482.70	
32	1 PC TAIL LAMP LH	560.50	
33	1 PC TAIL LAMP OUTER PANEL LH	466.70	
34	1 PC TAIL LAMP INNER PANEL LH	482.70	
35	1 PC REAR PANEL	560.80	
36	1 PC REAR PANEL TRIM	320.00	
37	1 PC REAR PANEL INNER TRIM	226.20	
38	1 PC REAR BUMPER	1,250.60	
39	2 PCS REAR BUMPER SIDE RETAINER	112.00	
40	1 PC REAR BUMPER REFLECTOR COVER- RH	61.60	
41	1 PC REAR BUMPER REFLECTORCOVER -LH	61.60	
42	2 PCS REAR BUMPER SPONGE	193.60	
43	1 PC REAR BUMPER REFLECTOR - LH	85.60	
44	1 PC REAR BUMPER REFLECTOR - RH	85.60	
45	1 PC REAR BUMPER TOWING COVER	26.50	
46	2 PCS REAR BUMPER PLASTIC SCREW	25.00	
47	1 PC SPARE TYRE PANEL	1,496.70	
48	1 PC SPARE TYRE PANEL CENTRE MEMBER	210.70	
49	1 PC SPARE TYRE PANEL JACK COVER	137.20	
50	1 PC SPARE TYRE PANEL INNER SPONGE	486.90	
51	1 PC SPARE TYRE TRAY	495.00	
52	1 PC SPARE TYRE TOP TRAY COVER	585.50	
53	1 PC REAR SPARE TYRE PANEL RH SIDE TRIM	155.70	
54	1 PC REAR SPARE TYRE PANEL RH SIDE COVER	122.80	
55	1 PC REAR SPARE TYRE PANEL LH SIDE TRIM	155.70	
56	1 PC REAR SPARE TYRE PANEL LH SIDE COVER	122.80	
57	1 PC EXHAUST PIPE	745.00	
58	1 PC BONNET	890.00	
59	2 PCS BONNET HINGE	98.60	
60	1 PC BONNET RUBBER	41.80	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200128
Date: 26 Apr 2022
Veh Reg No: SLV8501K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81200787
Reg. Date: 18/01/2018
Your Ref No: SMF2751S

Claim Type: Third Party
Accident Date: 21/04/2022
TP Veh Reg No: SMF2751S

Estimate Repair Cost to Vehicle No :SLV8501K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
61	1 PC BONNET LOCK	123.70	
62	1 PC BONNET LOCK TRIM	111.20	
63	1 PC FRT BUMPER	1,090.60	
64	1 PC FRT BUMPER REINFORCEMENT	366.70	
65	1 PC FRT BUMPER GRILLE	184.30	
66	1 PC FRT BUMPER COVER RH	43.00	
67	1 PC FRT BUMPER COVER LH	43.00	
68	2 PCS FRT BUMPER SIDE RETAINER	112.60	
69	1 PC FRT TOWING COVER	33.50	
70	1 PC FRT GRILLE	324.90	
71	1 PC FRT GRILLE EMBLEM	33.40	
72	1 PC FRT GRILLE TOP CHROME	335.90	
73	1 PC FRTGRILLE CHROM BOTTOM MOULDING	187.60	
74	1 PC FRT GRILLE CENTRE BRACKET	48.60	
75	1 PC HEADLAMP RH	1,815.60	
76	1 PC HEADLAMP RH BRACKET	46.00	
77	1 PC HEADLAMP LH	1,815.60	
78	1 PC HEADLAMP LH BRACKET	46.00	
79	1 PC HEADLAMP RETAINER RH	41.40	
80	1 PC HEAD LAMP RETAINER LH	41.40	
81	1 PC FRT SUPPORT PANEL	549.50	
82	1 PC AIRCON CONDENSER	843.30	
83	2 PCS AIRCON CONDENSER SIDE TRIM	62.60	
84	1 PC RADIATOR	1,491.70	
85	2 PCS RADIATOR UPPER BUSH	20.00	
86	2 PCS RADIATOR BOTTOM BUSH	20.00	
87	1 PC AIR CLEANER OUTLET AIR DUCT	61.20	
		32,590.20	
		Less 20%	6,518.04
			26,072.16

Special Net

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200128
Date: 26 Apr 2022
Veh Reg No: SLV8501K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81200787
Reg. Date: 18/01/2018
Your Ref No: SMF2751S

Claim Type: Third Party
Accident Date: 21/04/2022
TP Veh Reg No: SMF2751S

Estimate Repair Cost to Vehicle No :SLV8501K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
88	1 PC REAR WINDSCREEN SEAL	60.00	
89	1 PC REAR WINDSCREEN SEALANT	60.00	
90	2 SET REAR WINDSCREEN GARNISH CLIPS RH & LH	160.00	
91	1 PC REAR NUMBER PLATE	50.00	
92	1 PC REVERSE CAMERA	480.00	
93	1 SET BOOTLID TRIM CLIPS	40.00	
94	1 PC REAR WINDSCREEN VEDIO CAMERA	500.00	
95	1 PC REAR FENDER LH SEALANT	60.00	
96	1 PC REAR FENDER LH SEAL	60.00	
97	1 SET REAR FENDER TRIM CLIPS LH	60.00	
98	1 SET REAR FENDER TOP TRIM CLIPS LH	60.00	
99	1 SET REAR FENDER TRIM CLIPS RH	60.00	
100	1 SET REAR PANEL TRIM CLIPS	40.00	
101	1 SET REAR PANEL INNER TRIM CLIPS	30.00	
102	1 SET REAR BUMPER CLIPS	60.00	
103	1 SET REVERSE SENSORS	350.00	
104	1 SET BONNET RUBBER CLIPS	40.00	
105	1 SET BONNET LOCK TRIM CLIPS	30.00	
106	1 SET FRT BUMPER GRILLE CLIPS	40.00	
107	1 SET FRT BUMPER CLIPS	40.00	
108	1 PC FRT NUMBER PLATE	50.00	
109	1 SET FRT GRILLE CLIPS	40.00	
110	1 SET AIRCON CONDENSER SIDE TRIM CLIPS	40.00	
111	1 SET AIR CLEANER OUTLET AIR DUCT CLIPS	30.00	
		2,440.00	2,440.00
	Labour		
112	1 TO CHECK WIRING	50.00	
113	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
114	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	
115	1 TO REMOVE AND REFIT SPOLIER	150.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2200128
Date: 26 Apr 2022
Veh Reg No: SLV8501K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81200787
Reg. Date: 18/01/2018
Your Ref No: SMF2751S

Claim Type: Third Party
Accident Date: 21/04/2022
TP Veh Reg No: SMF2751S

Estimate Repair Cost to Vehicle No :SLV8501K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
116	1 TO REFIX THIRD BRAKE LIGHT	80.00	
117	1 TO REMOVE AND REFIT VEDIO CAMERA	80.00	
118	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
119	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
120	1 TO REMOVE AND REFIT INNER TRIM & CUSHION	180.00	
121	1 TO REMOVE AND REFIT REAR FENDER LH GLASS	120.00	
122	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	
123	1 TO SPRAY PANEL SEALANT	180.00	
124	1 (REAR) TO SPRAY PAINTING	1,800.00	
125	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	3,000.00	
126	1 TO CHECK WIRING	50.00	
127	1 TO REFILL AIRCON GAS	120.00	
128	1 TO SPRAY PANEL SEALANT	100.00	
129	1 (FRONT) TO SPRAY PAINTING	1,200.00	
130	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		8,940.00	8,940.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 21/04/2022
TP Veh Reg No: SMF2751S

Estimate No: EST2200128
Date: 26 Apr 2022
Veh Reg No: SLV8501K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81200787
Reg. Date: 18/01/2018
Your Ref No: SMF2751S

Estimate Repair Cost to Vehicle No :SLV8501K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 37,452.16
	Add GST @ 7%		2,621.65
	Total Amount Payable		<u><u>S\$ 40,073.81</u></u>

TOTAL: SINGAPORE DOLLAR FORTY THOUSAND SEVENTY THREE AND CENTS EIGHTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE