



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22003934/Evy3e2	
			Date: 19/05/2022	
			Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	FBK 5629Y
	Policy No.	D-21097290MFCE/93	Coverage (\$)	0.00
	Claim No.	D22000503MFCE	Excess (\$)	1,500.00
	Assign From	TEO KEE JIN	Assign Date	26/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400X	c.c	399
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JH2NC4797EK000430	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70Z R17	PIRELLI	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60Z R17	PIRELLI	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/06/2021	Inspection Date	27/04/2022
	Survey held at	48 TOH GUAN ROAD EAST #02-140		
	Repairer	COMFORTDELGRO ENGINEERING PTE LTD		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$8,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			