

Repair Quotation For FBN2977X

22.07.2022

PART NO	DESCRIPTION	QUANTITY	PRICE (\$)	
B74-F1711-00-P0	COVER SIDE 1	1	98	✓ CUT
B74-F171L-00-P0	MOLE SIDE COVER 1	1	58	X NN
B74-F1721-00-P0	COVER SIDE 2	1	58	✓ CUT
B74-F1731-00-P0	COVER SIDE 3	1	98	✓ CUT
B74-173B-00	EMBLEM 3D	2	98	✓ NEC
B74-F1741-00-P0	COVER SIDE 4	1	68	✓ CUT
B74-F2865-00-P0	COVER FRONT	1	118	✓ BR
B74-F414B-00	EMBLEM	2	48	✓ NEC
B74-F6145-00-P0	COVER HANDLE UPPER 2	1	78	✓ CUT
B74-F8351-00-P0	BODY COWLING	1	98	✓ BR
B74-F835J-00-P0	BODY FRONT UNDER 1	1	95	✓ BR
B74-F8377-00-P0	BODY COWLING 2	1	98	✓ BR
B74-H2129-00	COVER BATTERY	1	48	X NN
93399-99931	BEARING	1	98	✓ NEC
93399-99932	BEARING	1	118	✓ NEC
B74-E4411-01	CASE AIR CLEANER 1	1	110	✓ BR
B74-E4417-00	COVER 1	1	88	✓ CUT
B74-F1511-00	FENDE FRONT	1	76	✓ BR
B74-F3102-00	FRONT FORK ASSY LH	1	598	✓ BT
B74-F3103-00	FRONT FORK ASSY RH	1	598	✓ BT
B74-F3340-00	UNDER BRACKET COMP	1	698	✓ BT
B74-F6110-00	HANDLE COMP	1	108	✓ BT
B74-F6144-00	COVER HANDLEBAR LOWER	1	88	X NN
B74-F741L-00	BRACKER 4	1	138	✓ BR
B7-F8321-00	STAY 1	1	298	X NN
B74-H212B-00	BOX BATTERY 1	1	158	X NN
B74-H4300-00	HEADLIGHT ASSY	1	868	✓ BR
B74-H3500-30	METER ASSY	1	688	✓ BR

5141
-10%
4626.90

B74-E5431-00	CRANKCASE COVER 3	1	58	✓	BR
KAPPA VENTURE 58	TOP CASE	1	540	✓	DD
KAPPA BASEPLATE	BASEPLATE	1	90	✓	BR
IU UNIT	IU	1	185.7	✗	NN
MIRROR AND BRACKET	MIRROR AND IU BRACKET	1	298	✓	NEC
TOTAL			6962.7		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

On "Without Prejudice" Basis

p/p ~~L~~ sum repair
4 repair days

986
= 6127
- 10%
5514.30

Supplementary

ADDITIONAL ITEMS

PART NO	DESCRIPTION	QUANTITY	PRICE (\$)
B74-F836K-00	METER COVER / -BR	1	\$58
-	FRONT RIM / CUT	1	\$358
-	RIM BEARING / RC	2	\$30
-	L VALVE / RC	2	\$35
-	Labour INSPECTION FEE	1	\$20
-	" TOWING FOR INSPECTION	2	\$90
-	" ADMIN FEE FOR INSPECTION	1	\$30
TOTAL			\$621

481

-10%

432.90

labour

140

5514.30

6087.20

Stew (LKK) 83228813/67418434

28/10/22, 2.12pm