

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : TOKIO MARINE INSURANCE (S) LTD
20 MCCALLUM STREET
#09-01 TOKIO MARINE CENTRE
SINGAPORE 069046
TEL: 62216111 FAX: 62212101
ATTN: Motor Claim Department

WS Ref: TP/TOKIO/AMK
Claim Type: Third Party
Accident Date: 22/04/2022
TP Veh Reg No: WD4605K

Estimate No: ES2290418/AMK
Date: 27 Apr 2022
Policy No: 5074943539-05 DC
Veh Reg No: SKW320A
Make/Model: TOYOTA COROLLA
FIELDER

Chassis No: NRE1618000977
Engine No: 2NR8498784
Reg. Date: 14/10/2015

*Not authorized
11 Rm @ 4400/-
Return After Paint
5 days*

Estimate Repair Cost to Vehicle No :SKW320A

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER <i>563.10</i>	563.10	1 PC	<i>Bu</i> 563.10	<i>✓</i>
2 FRONT BUMPER RH SIDE RETAINER	61.00	1 PC	<i>cm</i> 61.00	<i>✓</i>
3 FRONT BUMPER CLIP	4.80	6 PC	<i>na</i> 28.80	<i>✓</i>
4 HEADLAMP RH <i>1029.70</i>	<i>my Bu</i> 1,029.70	1 PC	1,029.70	<i>✓</i>
5 HEADLAMP RH TOP PANEL	126.70	1 PC	<i>Bu</i> 126.70	<i>✓</i>
6 HEADLAMP RH CHROME	141.75	1 PC	<i>su</i> 141.75	<i>X</i>
7 FRONT RH FENDER	814.70	1 PC	<i>Ry</i> 814.70	<i>✓</i>
8 FRT RH FENDER INNER SHIELD	188.10	1 PC	<i>cm</i> 188.10	<i>✓</i>
9 FRONT RH FENDER INNER SHIELD CLIP	2.31	6 PC	<i>na</i> 13.86	<i>✓</i>
10 BONNET <i>926.30</i>	926.30	1 PC	<i>Ry</i> 926.30	<i>✓</i>
11 BONNET INSULATOR	85.30	1 PC	<i>su</i> 85.30	<i>X</i>
12 BONNET HINGE <i>ols dri</i>	62.40	2 PC	124.80	<i>✓</i>
13 FRONT WIPER PANEL GARNISH	771.90	1 PC	<i>su</i> 771.90	<i>X</i>
14 FRONT WIPER PANEL RH SIDE EXTENSION	57.80	1 PC	<i>dri</i> 57.80	<i>✓</i>
15 FRONT RH SHOCK ABSORBER	575.90	1 PC	<i>su</i> 575.90	<i>X</i>
16 FRONT RH KNUCKLE ARM <i>630.80</i>	630.80	1 PC	<i>Ry</i> 630.80	<i>✓</i>
17 FRONT RH KNUCKLE BEARING	195.20	1 PC	<i>na</i> 195.20	<i>✓</i>
18 FRONT RH STAY LINKAGE	226.50	1 PC	<i>su</i> 226.50	<i>X</i>
19 FRONT RH LOWER ARM	1,269.70	1 PC	<i>su</i> 1,269.70	<i>X</i>
20 WIPER WASHER TANK	154.60	1 PC	<i>su</i> 154.60	<i>X</i>
			7,986.51	
	Less 25%		1,996.63	5,989.88

Special Net

21 FRONT RH RIM	350.00	1 PC	<i>Red</i> 350.00	<i>250.00</i>
			350.00	350.00

Labour

22 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,HEADLAMP,FRT RH FENDER,KNOCKING & REPAIR FRT RH FENDER INNER PANEL & REALIGN FRT RH DOOR THE SAME	700.00	1 LA	700.00	<i>600</i>
23 PUTTY & RESPRAY FRT BUMPER,BONNET & ATTACHMENTS,FRT RH FENDER & INNER PANEL,HEADLAMP TOP PANEL,FRT RH DOOR & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	<i>900</i>
24 REMOVE & REFIX FRT RH RIM,UNDERCARRIAGE & REALIGN THE SAME	180.00	1 LA	180.00	<i>600</i>

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : TOKIO MARINE INSURANCE (S) LTD
20 MCCALLUM STREET
#09-01 TOKIO MARINE CENTRE
SINGAPORE 069046
TEL: 62216111 FAX: 62212101
ATTN: Motor Claim Department

WS Ref: TP/TOKIO/AMK
Claim Type: Third Party
Accident Date: 22/04/2022
TP Veh Reg No: WD4605K

Estimate No: ES2290418/AMK
Date: 27 Apr 2022
Policy No: 5074943539-05 DC
Veh Reg No: SKW320A
Make/Model: TOYOTA COROLLA
FIELDER
Chassis No: NRE1618000977
Engine No: 2NR8498784
Reg. Date: 14/10/2015

Estimate Repair Cost to Vehicle No :SKW320A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
25 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
26 RUSTPROOFING	60.00	1 LA	60.00	✓
27 TOWING	(B.11) 70.00	1 LA	70.00	✓
			2,070.00	2,070.00
Total				S\$ 8,409.88
Add GST @ 7%				588.69
Total Amount Payable				<u><u>S\$ 8,998.57</u></u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: