

ASS. REQ. BY:

REF: CWF/Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW 320AYr Regn: 10.1.15Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Fielder

C.C.

1496

Colour:

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

37110

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NRE161.8000977Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/4/22

D.O.L.

27/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRN O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : TOKIO MARINE INSURANCE (S) LTD
20 MCCALLUM STREET
#09-01 TOKIO MARINE CENTRE
SINGAPORE 069046
TEL: 62216111 FAX: 62212101
ATTN: Motor Claim Department

WS Ref: TP/TOKIO/AMK
Claim Type: Third Party
Accident Date: 22/04/2022
TP Veh Reg No: WD4605K

Estimate No: ES2290418/AMK
Date: 27 Apr 2022
Policy No: 5074943539-05 DC
Veh Reg No: SKW320A
Make/Model: TOYOTA COROLLA
FIELDER
Chassis No: NRE1618000977
Engine No: 2NR8498784
Reg. Date: 14/10/2015

Not attached
1/1 Rm B
Returning After Paint
5-6 days

Estimate Repair Cost to Vehicle No :SKW320A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	563.10	1 PC	<i>Bu</i> 563.10	✓
2 FRONT BUMPER RH SIDE RETAINER	61.00	1 PC	<i>CM</i> 61.00	✓
3 FRONT BUMPER CLIP	4.80	6 PC	<i>ru</i> 28.80	✓
4 HEADLAMP RH	<i>my Bu</i> 1,029.70	1 PC	1,029.70	✓
5 HEADLAMP RH TOP PANEL	126.70	1 PC	<i>Bu</i> 126.70	✓
6 HEADLAMP RH CHROME	141.75	1 PC	141.75	?
7 FRONT RH FENDER	814.70	1 PC	<i>Ry</i> 814.70	✓
8 FRT RH FENDER INNER SHIELD	188.10	1 PC	<i>CM</i> 188.10	✓
9 FRONT RH FENDER INNER SHIELD CLIP	2.31	6 PC	<i>ru</i> 13.86	✓
10 BONNET	926.30	1 PC	<i>Ry</i> 926.30	✓
11 BONNET INSULATOR	85.30	1 PC	85.30	?
12 BONNET HINGE	<i>old dri</i> 62.40	2 PC	124.80	✓
13 FRONT WIPER PANEL GARNISH	771.90	1 PC	771.90	?
14 FRONT WIPER PANEL RH SIDE EXTENSION	57.80	1 PC	<i>dri</i> 57.80	✓
15 FRONT RH SHOCK ABSORBER	575.90	1 PC	575.90	?
16 FRONT RH KNUCKLE ARM	630.80	1 PC	630.80	?
17 FRONT RH KNUCKLE BEARING	195.20	1 PC	195.20	?
18 FRONT RH STAY LINKAGE	226.50	1 PC	<i>sm</i> 226.50	X
19 FRONT RH LOWER ARM	1,269.70	1 PC	1,269.70	?
20 WIPER WASHER TANK	154.60	1 PC	<i>sm</i> 154.60	X
			7,986.51	
		Less 25%	1,996.63	5,989.88
Special Net				
21 FRONT RH RIM	350.00	1 PC	<i>Red</i> 350.00	<i>250.00</i>
			350.00	350.00
Labour				
22 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,HEADLAMP,FRT RH FENDER;KNOCKING & REPAIR FRT RH FENDER INNER PANEL & REALIGN FRT RH DOOR THE SAME	700.00	1 LA	700.00	<i>600</i>
23 PUTTY & RESPRAY FRT BUMPER,BONNET & ATTACHMENTS,FRT RH FENDER & INNER PANEL,HEADLAMP TOP PANEL,FRT RH DOOR & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	<i>900</i>
24 REMOVE & REFIX FRT RH RIM,UNDERCARRIAGE & REALIGN THE SAME	180.00	1 LA	180.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : TOKIO MARINE INSURANCE (S) LTD
20 MCCALLUM STREET
#09-01 TOKIO MARINE CENTRE
SINGAPORE 069046
TEL: 62216111 FAX: 62212101
ATTN: Motor Claim Department

Estimate No: ES2290418/AMK
Date: 27 Apr 2022
Policy No: 5074943539-05 DC
Veh Reg No: SKW320A
Make/Model: TOYOTA COROLLA
FIELDER
Chassis No: NRE1618000977
Engine No: 2NR8498784
Reg. Date: 14/10/2015

WS Ref: TP/TOKIO/AMK
Claim Type: Third Party
Accident Date: 22/04/2022
TP Veh Reg No: WD4605K

Estimate Repair Cost to Vehicle No :SKW320A

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
25 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
26 RUSTPROOFING	60.00	1 LA	60.00	✓
27 TOWING	(Bill) 70.00	1 LA	70.00	✓
			2,070.00	2,070.00
Total				S\$ 8,409.88
Add GST @ 7%				588.69
Total Amount Payable				<u>S\$ 8,998.57</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/04/2022 19:22 (SGT)
Date of Accident	22/04/2022 14:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ELITE PARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW320A

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN POH SIEW
NRIC No	SXXXX270G
Email Address	tanpsisaac@gmail.com
Mobile Phone No	(Phone) +65-97889438
Alternative Phone No	+65-97889438

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	FIELDER
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496


INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5074943539-05 DC
Cover Note Number	14/10/2020 - 13/10/2021

DRIVER

Name of Driver	TAN POH SIEW
NRIC No	SXXXX270G

Sketch Plan



A: SKW320A
(Alone)

B: WD4605K

C: Mr David - 9423 4797

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SKW320A (NTUC)

Date & Time: 22/04/2022 @ 1410 (clear day)

I was guided by Worker to proceed to move forward, a few seconds later, I saw the Sweeper arm swinging towards my direction and hit onto the front RH portion of my car. I put my car to the roadside, took some scene photos and exchange particulars with the Worker in charge of the Sweeper (WD4605K). My car was arranged to tow to NTUC authorized workshop for accident report and damage assessment.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

22/4/2022 4:15 pm
Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()